



RENAULT MEGANE BERLINE: GJ-238-KM

Vinnumber:	VF1RFB00X69170614	Versionname:	RENAULT MEGANE BERLINE Business TCe 140 EDC FAP -21N VP [5P] bva 7-140CH-7cv (bi-corps)	
First Registrationdate:	14/09/2022	Fiscalpower:		
Expertise Mileage:	157269	Power Kw:	103	
Bodytype:	Berline	Body colour:	Black	
Gearbox:	Automatic	Paint type:	Metallic	
Transmission:	Front	Interior colour:	Black	
Fueltype:	Petrol	Type of rims (mounted):	Steel	
Engine functioning:	Yes	Dashboard color:	Black	
Battery functioning:	Yes			
Vehicle running:	Yes			
Number of doors:	5			
Number of seats:	5			
Number head rests:	5			
Type of rims (mounted):	Steel			
Category:	Passenger Car			

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

205/55/16 94 V				
Summer tyres:	Fr.L.	Pirelli: 90%	Fr.R.	Pirelli: 90%
	Re.L.	Pirelli: 50%	Re.R.	Pirelli: 55%
Tyre profile depth FL				2.2
Tyre profile depth FR				2.0
Tyre profile depth RL				5.0
Tyre profile depth RR				4.6
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Interior covering B pillar L, Scratch(es), Replace



Interior, Stain, Cleaning



Armrest F M, Burned, Replace



Tyre FL, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Door FL, Bad repair, Paint



Door RL, Bad repair, Paint



Outer sill L, Bad repair, Paint



Wing RL, Bad repair, Repair and paint (complete)



Bumper F, Scratch(es), Paint



Bumper moulding FR, Scratch(es), Replace



Windscreen, Stone chip(s), Windscreen repair



Wing RR, Bad repair, Paint



Door RR, Bad repair, Paint



Outer sill R, Bad repair, Paint



Door FR, Bad repair, Repair and paint (complete)



Roof pillar R, Bad repair, Paint



Rubber seal for boot lid, Tear, Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Bad repair, Paint



Aerial, Missing, Replace



Historique Maintenance

Immatriculation: **GJ-238-KM** Date de 1ère immatriculation: **14/09/2022**

Modèle: **Renault MÉGANE BERLINE Business TCe 140 EDC FAP -21N VP [5P] bva 7-140CH-7cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
26/11/2025	140.099	@ AUTOMOBILES SARL	RECYCLAGE
	0		DIAG
	0		ESSAI
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		COURROIE ACCESSOIRES RPLT
	0		DIVERS
	0		KIT ACCESSOIRES RPLT
	0		POMPE A EAU RPLT
28/08/2025	129.102	@ AUTOMOBILES SARL	HUILE BV RPLT
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		RECYCLAGE
10/02/2025	102.760	@ AUTOMOBILES SARL	PLAQUETTES AR RPLT
	0		RECYCLAGE
	0		REVISION ET CLIM
18/06/2024	69.999	LORENTE AUTOMOBILES	REVISION ET CLIM ET AIR ET CARBURANT
	0		DISQUES PLAQUETTES AV RPLT
20/09/2023	36.218	LORENTE AUTOMOBILES	BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		REVISION ET CLIM