

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	313937
License plate	2CBV570
Vehicle identification number	VSSZZZKJZNR105336
Dossier	2022 045 024
Make	Seat Arona 1.0 81kW Move DSG
Mileage	106972
First registration	25/05/2022
client availability date	28/05/2026
inspectionDate	06/06/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	N
13	Bumper Front // Painting	Y
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
100	Door Rear Left // Smart Repair Small	Y
107	Door Rear Left / Trim / Replace	Y
124	Light / Rear left / Replace	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
148	Back Side / Reflector R / Replace	Y
153	Rear Bonnet // Painting	N
175	Light / Rear Right On Rear Bonnet / Replace	Y
237	Wing Front right / Trim / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
534	Trunk Compartment / Carpet / Replace	Y
553	Central Console / Gear Lever / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	Y

## Damage Pictures



Bumper Front // Painting-scratch



Wing Front right / Trim / Replace-scratch




Trunk Compartment / Carpet / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Left // Smart Repair Small-dent



Door Rear Left / Trim / Replace-tear




Door Front Left / Trim / Replace-tear




Interior Cleaning // Small-stain



Central Console / Gear Lever / Replace-worn



Back Side / Reflector R / Replace-scratch



Rear Bonnet // Painting-scratch




Light / Rear Right On Rear Bonnet / Replace-scratch



Bumper Rear // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Light / Rear left / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Side View Mirror Left // Painting-scratch