MACADAM








Seat Ateca (UKL): 2CLD545

Vinnumber:	**VSSZZZ5FZN6534539**	Versionname:	**Ateca Move! 1.0TSi 110pk/cv 5p**
First Registrationdate:	**1/09/2022**	Fiscalpower:	
Expertise Mileage:	**122180**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**18500 km - 520 dagen**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/55/17/98 W**			
	Fr.L.	**Vredestein: 3 mm**	Fr.R.	**Vredestein: 3 mm**
	Re.L.	**Goodyear: 5 mm**	Re.R.	**Goodyear: 5 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**215/55 R 17 98 W**
Tyre size FR	**215/55 R 17 98 W**
Tyre size RL	**215/55 R 17 94 V**
Tyre size RR	**215/55 R 17 94 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

MOT certificate, Missing, Replace




Windscreen, Stone chip(s), Windscreen repair




Windscreen, Stone chip(s), Acceptable




Bonnet, Dent(s) and scratch(es), Acceptable


Bumper F, Scratch(es), Acceptable






Wing FL, Scratch(es), Acceptable




Alloy rim FL, Scratch(es), Acceptable




Door FL, Dent(s) and scratch(es), Acceptable








Door RL, Scratch(es), Acceptable




Door RL, Dent(s), Acceptable

Wing RL, Dent(s) and scratch(es), Acceptable



Boot cover, Broken, Forfeit




Tailgate / Boot, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable






Wing RR, Dent(s) and scratch(es), Acceptable





Door RR, Dent(s) and scratch(es), Acceptable







Door trim RR, Scratch(es), Acceptable

Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)




Roof pillar R, Dent(s), Acceptable




Wing FR, Dent(s), Repair and paint (complete)




Bodywork, Not original part, Remove lettering



Onderhoudshistorie van: VSSZZZ5FZN6534539

ALPHABET

Kenteken	2CLD545
Merk Model	Seat Ateca Move! 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	9/1/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/26/26	107,653	0139-Aanvulling op onderhoudsbeurt	Uitvoeren
2/26/26	107,653	bougie	Vervangen
2/26/26	107,653	klein materiaal	
2/26/26	107,653	koelwatervloeistof	Bijvullen/-laden
2/26/26	107,653	luchtfilter	Vervangen
2/26/26	107,653	luchtfilter interieur	Vervangen
2/26/26	107,653	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
2/26/26	107,653	remschijven en blokken achter	Vervangen
2/26/26	107,653	remschijven en blokken vooraan	Vervangen
2/26/26	107,653	remvloeistof	Bijvullen/-laden
2/26/26	107,653	ruitenwisserrubber achter	Vervangen
2/26/26	107,653	ruitenwisserrubber vooraan	Vervangen
2/26/26	107,653	ruitenwisservloeistof	Bijvullen/-laden
3/17/25	78,493	diagnose	Uitvoeren
3/17/25	78,493	klein materiaal	
3/17/25	78,493	Onderhoudsbeurt (variabel interval)	Uitvoeren
3/17/25	78,493	ruitenwisserrubber achter	Vervangen
3/17/25	78,493	ruitenwisserrubber vooraan	Vervangen
4/11/24	57,895	0139-Aanvulling op onderhoudsbeurt	Uitvoeren
4/11/24	57,895	bougie	Vervangen
4/11/24	57,895	klein materiaal	
4/11/24	57,895	luchtfilter interieur	Vervangen
4/11/24	57,895	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
4/11/24	57,895	ruitenwisservloeistof	Bijvullen/-laden
6/27/23	27,138	klein materiaal	
6/27/23	27,138	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
6/27/23	27,138	ruitenwisserrubber vooraan	Vervangen
6/27/23	27,138	ruitenwisservloeistof	Bijvullen/-laden