



FORD Tourneo Courier: 8635-MRP

Vinnumber:	WF01NBER71RR11543	Versionname:	1.0 Ecoboost 92kW (125CV) Trend monovolumen compacto 92kW 5P manual
First Registrationdate:	27/05/2024	Fiscalpower:	
Expertise Mileage:	111400	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Petrol		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	1	Central consol F
Number keys remote:	1	Luggage cover
Windows electric F:		Rear parking sensors
Cruise Control:		
Steering wheel multifunctional:		
Radio multimedia:		
Type of climate control:	Autom climate control	

Tyres

195/65/15/91 V				
Summer tyres:	Fr.L.	Other: 8 mm	Fr.R.	Other: 5 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm
Tyre profile depth FL				8.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/65 R 15 91 V
Tyre size FR				195/65 R 15 91 V
Tyre size RL				195/65 R 15 91 V
Tyre size RR				195/65 R 15 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Interior, Dirty, Cleaning





Boot lid covering R, Scratch(es), Replace



User's manual, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Roof liner, Scratch(es), Replace



Floor covering FL, Burned, Replace



Rear light L, Crack, Replace



Wing RL, Scratch(es), Paint



Wing FL, Scratch(es), Paint



Wing FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Windscreen, Stone chip(s), Forfeit



Outside rear-view mirror housing R, Scratch(es), Acceptable



Wing RR, Dent(s), Repair and paint (complete)



Sliding door R, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Tailgate / Boot, Scratch(es), Paint



Tyres, No damage, Check



