




IDENTIFICATION VEHICLE

Driver name:
Make: SKODA
Model / version: SUPERB COMBI DIESEL - 2019
Vin: TMBJH7NP2M7054943
Plate: 2AEE022
Mileage: 131454
First registration: 05/03/2021
Color: Lava Blue




ADDITIONAL INFORMATION




Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 1
Original key: ✓

PICTURES





VIN INFORMATION

8 haut-parleurs
 Pommeau de levier de vitesses cuir
 2021
 Projecteurs antibrouillard
 Matière : alliage
 Diamètre arrière 16
 Diamètre avant 16
 Hauteur arrière 60
 Largeur avant 215
 Climatisation réfrigérant 1234YF
 Ordinateur de bord
 2.00 litres
 Alternateur 180 Ampères
 Rétroviseur droit à réglage mémorisé
 Rétroviseurs rabattables électriques

Transmission séquentielle
 5 portes
 Janvier
 Essue-lunette arrière
 Lettre repère (J)
 Largeur avant 6,5
 Diamètre arrière 16
 Indice de vitesse avant V
 Largeur arrière 215
 Accoudoir central arrière
 Diesel
 110 kw
 Métallisée vernissée
 Rétroviseur gauche jour/nuit automatique
 Rétroviseur intérieur jour et nuit

7 rapports
 Break
 Projecteurs à allumage automatique
 Entourage de vitres chromé
 Diamètre avant 16
 Largeur arrière 6,5
 Hauteur avant 60
 Indice de vitesse arrière V
 Climatisation automatique 2 zones
 Finition intérieure Aluminium
 1968 cm3
 150 ch
 Rétroviseur gauche à réglage mémorisé
 Rétroviseur droit jour/nuit automatique
 Siège avant gauche chauffant

Sièges avant chauffants	Siège avant gauche à réglage électrique	Siège avant gauche à réglage lombaire
Volant cuir	Volant multifonction	Aide au stationnement avant
Aide au stationnement arrière	Caméra arrière de recul	Régulateur et limiteur de vitesse
Régulateur automatique de la distance	Equipement Stop & Start	Ouverture du coffre électriquement
Pare-brise athermique	Lunette arrière teintée foncée	Vitres portes arrière teintées foncées
Vitres de custode teintées foncées	détecteur de pluie essuie-vitre	Attelage avec boule amovible
Fixotoit	Freinage d'urgence assistée autonome (urbain)	sécurité enfants électrique
insonorisation étendue	volant avec masse d'équilibrage	gicleurs lave-glace chauffants
grille de protection radiateur avec moulures chromées	spoilers latéraux au niveau du pavillon (seulement pour Combi)	ceintures de sécurité avec système d'avertissement optique et acoustique
Keyless-Go	roues av motrices (traction)	système de gonflage des pneus
catalyseur SCR	radio avec récepteur digital	airbag pour les genoux
norme anti-pollution Euro 6 AP	entretien à intervalle flexible (Long Life) QI6	

EQUIPMENT			
Board computer:		Central locking:	
Compressor:		Cruise control:	
Gps:		Power steering:	
Rear parking sensor:		Repair kit:	
Front seats heated:		Steering wheel:	
Electric windows:		Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES						
Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Winter		
Front right	5 mm			Winter		
Rear left	5 mm			Winter		
Rear right	5 mm			Winter		

DAMAGES SUMMARY		
NOT ACCEPTABLE / TO BE INVOICED		
#	Location	Damage type
1	Interior	Dirty
2	Contact key	Missing
3	Bumper F	Grooved
4	Bonnet	Scratch(es)
5	Alloy rim FL	Grooved
6	Outside rear-view mirror housing L	
7	Wing FL	Scratch(es)
9	Wing RL	Dent(s) and scratch(es)
10	Alloy rim RL	Grooved
11	Bumper R	Grooved
12	Tailgate / Boot	Dent(s) and scratch(es)
13	Alloy rim RR	Grooved
14	Door FR	Scratch(es)
15	Roof	Chemical polution
16	Alloy rim FR	Grooved

Total: 15
ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
8	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS


1 - Interior - Dirty



2 - Contact key - Missing



3 - Bumper F - Grooved



4 - Bonnet - Scratch(es)



5 - Alloy rim FL - Grooved






6 - Outside rear-view mirror housing L



7 - Wing FL - Scratch(es)



9 - Wing RL - Dent(s) and scratch(es)





10 - Alloy rim RL - Grooved




11 - Bumper R - Grooved



12 - Tailgate / Boot - Dent(s) and scratch(es)





13 - Alloy rim RR - Grooved



14 - Door FR - Scratch(es)



15 - Roof - Chemical polution



16 - Alloy rim FR - Grooved



8 - Bodywork - Dent(s) and scratch(es) - Renta®





SIGNATURE

Expert

04/08/2026 09:29