



Expertise

Protocol number: 46511706  
Order No. / Reference: 26561838  
Inspection date: 9 Jul 2026

Manufacturer: Volkswagen

Model: Touran 2.0 TDI SCR DSG Highline

VIN: WVGZZZ1TZNW011561



| Vehicle details                            |                         |
|--------------------------------------------|-------------------------|
| Manufacturer / Type / Model / Equipment    |                         |
| Volkswagen Touran 2.0 TDI SCR DSG Highline |                         |
| Vehicle Identification number              | WVGZZZ1TZNW011561       |
| Mileage (Read)                             | 141,950 km              |
| First registration                         | 17 May 2022             |
| Number of holders                          | 1                       |
| Power / Engine displacement                | 110 kw / 1,968 ccm      |
| Fuel type / Cylinder                       | Diesel / 4              |
| Gearbox / Number of gears                  | Automatic / 7           |
| Type of drive                              | Front drive             |
| Type of vehicle                            | Van                     |
| Colour / colour code                       | Oryxweiß Perlmutteffekt |
| Doors / Seats                              | 5 / 5                   |
| Upholstery type                            | Cloth                   |
| Colour of upholstery                       | Black                   |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete     | <b>Next maintenance in</b>     | 7,100 km                                                   |
| <b>Last service on / at</b>                      | 03/2026 at 137,355 km        |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                              | <b>Letter No.</b>              | GJ149967                                                   |
| <b>Previous damage / Accident</b>                | None detectable              | <b>Repainting</b>              | Detectable                                                 |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | No                                                         |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 0603 / BWR 00362             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,230 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 215/55 R17 94V | Summer tyres on Light alloy | Continental  | 6mm / 6mm   |
| 2) | 215/55 R17 94V | Summer tyres on Light alloy | Continental  | 4mm / 4mm   |

### Additional tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 205/60 R16 96H | Winter tyres on Light alloy | Continental  | 6mm / 6mm   |
| 2) | 205/60 R16 96H | Winter tyres on Light alloy | Continental  | 6mm / 6mm   |

### Replacement

| Typ | Tyre size      | Type of tyre          | Manufacturer | Tread depth |
|-----|----------------|-----------------------|--------------|-------------|
| E   | 205/60 R16 96V | Summer tyres on Steel | Pirelli      | 7 mm        |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- 2 USB-C ports on the front
- Storage compartments in the overhead console
- Airbag, head airbag system for front and rear passengers
- Electrically adjustable and heated exterior mirrors
- third brake light
- Headliner in Storm Grey
- Decorative inlays "Piano Black"
- Tachometer
- Electronic parking brake including auto-hold function
- Windscreen in heat-insulating glass
- Baggage management package
- Additional luggage compartment lighting
- Speed limiter
- Glove compartment with cooling option
- Rear window wiper with intermittent function
- ISOFIX mounting points on rear seats
- Air conditioning system "Air Care Climatronic"
- Front headrests
- LED headlights
- Illuminated makeup mirrors in the sun visors
- front center armrest
- Fatigue detection
- Non-smoking version
- Emergency call service
- Package: Winter Package
- Proactive occupant protection system in conjunction with "Front Assist"
- Radio accessories: Digital radio reception DAB+
- Wheels: Tire Mobility Set omitted
- Automatically heated front windshield washer nozzles
- Drawers under the front seats
- Seat belts: 3 three-point automatic seat belts in the rear
- Seats: Front passenger seat backrest folds down completely
- Seats: Top comfort seats in the front
- Start-stop system
- Bumpers in body color
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: Discover Media navigation function incl. streaming & internet
- Electronic immobilizer
- Green thermal insulation glazing
- Storage compartment with lid on the instrument panel
- Airbag for driver and front passenger
- Airbag: Side airbags for the outer rear seats
- Exterior mirror housings and door handles in body color
- Chrome trim on the side windows
- Roof rails, silver anodized
- Diesel particulate filter
- Parking assistance
- Electronic Stability Program (ESP) with counter-steering support
- luggage compartment cover
- Height-adjustable luggage compartment floor
- Transmission: 7-speed DSG
- Rear window heated
- Interior lights with delayed shut-off and dimming function, 2 reading lights front and rear
- Headrests (3) in the 2nd row of seats
- Black radiator grille with chrome strips on the slats
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- "Premium" multifunction display with multicolor screen
- Fog lights and cornering lights
- Emergency braking assistant "Front Assist"
- Package: Ambient lighting
- Upholstery: Cloth
- Radio
- Radio accessories: 8 speakers
- Tire pressure monitoring system (passive)
- Gearshift knob in leather
- Headlight cleaning system
- electromechanical power steering
- Seats: 3 individual seats in the 2nd row
- Seats: Folding tables on the backs of the front seats
- Seats: Lumbar support in the front
- Seats: Front seats are height-adjustable
- 12V power outlet on the rear of the center console
- Textile floor mats
- Prepared for "We Connect" and "We Connect Plus"
- Washer fluid level warning light
- Warning tone and light for unfastened seat belts front and rear
- Central locking without safe locking, with remote control and 2 remote folding keys



## Extra equipment

- Towbar, foldable with electric release
- Digital Cockpit Pro (instrument cluster as TFT display with interactive display - various information profiles are selectable (e.g. consumption & range, navigation, driver assistance, efficiency))
- Paint finish: Pearlescent effect
- Package: Business Premium (Air Care Climatronic, combination filter - ACC stop & go, speed limiter, Front Assist - lumbar support front, driver's side electrically adjustable with massage function - multifunction leather steering wheel, paddle shifters - cargo net partition - heated windshield washer nozzles - headlight cleaning system - drawer under right front seat - microfleece seat center panels - heated top comfort seats front - emergency braking assistant "Front Assist" - height-adjustable front seats, ergoActive seat on the driver's seat - washer fluid warning light.)
- Wheels: Light alloy (4) "Salvador" 6.5 J x 17 Volkswagen R (4 light alloy wheels 6.5Jx17 in grey metallic - tires 215/55 R 17, rolling resistance class A - with individual installation - wheel locks with extended theft protection)
- Wheels: Space-saving spare wheel, steel 6.5 J x 16, for 17- and 18-inch alloy wheels (on-board tools and jack)
- Rear side windows and rear window tinted
- Auxiliary heating and ventilation (auxiliary heating and ventilation with radio remote control and timer)
- Adaptive Cruise Control ACC "stop & go" up to 210 km/h and Emergency Brake Assist "Front Assist" (Adaptive Cruise Control ACC "stop & go", with speed limiter - Emergency Brake Assist "Front Assist" (for Adaptive Cruise Control ACC up to 210 km/h))
- Navigation system "Discover Media" incl. "Streaming & Internet" (screen diagonal 20.3 cm - touchscreen - FM radio reception - dual tuner with phase diversity - MP3 playback - SD card slot - USB-C with Apple compatibility - output power 4x20 watts - map with 2D display - traffic sign display - telephone interface - 3-way sound control - DAB+ digital radio reception)
- Package: Family (foldable and removable reversible luggage compartment mat - electric child safety lock for rear doors, operable from the driver's seat - sunshade roller blind on the rear door windows)
- Package: Mirror package (electrically folding exterior mirrors, auto-dimming on the driver's side, ambient lighting and passenger-side exterior mirror lowering - automatic headlight control with daytime running lights, "Leaving home" function and manual "Coming home" function - automatically dimming interior mirror - rain sensor)
- Voice control
- "Comfort" telephone interface with inductive charging function (hands-free system)

## Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                                  |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |

## Value reducing factors

| No. | Component group              | Description                                   |
|-----|------------------------------|-----------------------------------------------|
| 1   | Wing mirror - left side      | Cap - Scratch(es) - Smart repair              |
| 2   | Side panel - rear right side | Sill - dent(s) - Smooth repair work           |
| 3   | Side panel - rear left side  | Sill - Dent / paintcoat damage - Smart repair |

## Wear and tear

| No. | Component group | Description                         |
|-----|-----------------|-------------------------------------|
| 1   | Bonnet          | Bonnet - Stone chips - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.



## Repainting

### No. Repainting

1 Door - front left side, Professionally carried out, Invoice of repair done Non-existent

## Paint coat thickness measurement

Door - front left side 207 µm

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.





Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres





Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.






Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.






**Figure 25:** Misc.



**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.



**Damage 1:** Wing mirror - left side: Cap - Scratch(es) - Smart repair




**Damage 1:** Wing mirror - left side: Cap - Scratch(es) - Smart repair



**Damage 2:** Side panel - rear right side: Sill - dent(s) - Smooth repair work



**Damage 2:** Side panel - rear right side: Sill - dent(s) - Smooth repair work



**Damage 3:** Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



**Damage 3:** Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



**Damage 3:** Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



**Wear and tear 1:** Bonnet: Bonnet - Stone chips - No deduction





**Wear and tear 1:** Bonnet: Bonnet - Stone chips - No deduction



**Repainting 1:** Door - front left side



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZ1TZNW011561

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Touran 2.0 TDI SCR DSG  
Highline

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                                                                                                                |
|------------|----------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 24.03.2026 | 137.355  | Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben hinten; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                             |
| 02.12.2025 | 127.007  | Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges                                                                                                                                                                                                       |
| 05.05.2025 | 105.741  | AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                                                                |
| 09.01.2025 | 95.050   | Systemtest/Eigendiagnose                                                                                                                                                                                                                                                                    |
| 28.06.2024 | 80.696   | Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges |
| 22.09.2023 | 54.967   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                                                                    |
| 11.01.2023 | 27.005   | Motoröl b. Wartung; Regelwartungsdienst                                                                                                                                                                                                                                                     |