MACADAM









VOLKSWAGEN T-ROC: GK-796-QR

Vinnumber:	**WVGZZZA1ZPV581663**	Versionname:	**VOLKSWAGEN T-ROC 1.0 TSI 110 LIFE BUSINESS VP [5P] bvm 6-110CH-6cv (SUV)**
First Registrationdate:	**21/11/2022**	Fiscalpower:	
Expertise Mileage:	**139688**	Power Kw:	**81**
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Other**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**215/60/19/99 H**			
	Fr.L.	**Dunlop: 55%**	Fr.R.	**Dunlop: 55%**
	Re.L.	**Dunlop: 10%**	Re.R.	**Dunlop: 10%**

Tyre profile depth FL	**4.6**
Tyre profile depth FR	**4.5**
Tyre profile depth RL	**7.6**
Tyre profile depth RR	**7.5**
Tyre size FL	**215/60 R 19 99 H**
Tyre size FR	**215/60 R 19 99 H**
Tyre size RL	**215/60 R 19 99 H**
Tyre size RR	**215/60 R 19 99 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**257**
Tyre make FR	**257**
Tyre make RL	**257**
Tyre make RR	**257**

Assistance equipment

Emergency spare wheel	**Yes**	Jack	**Yes**

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Outer door handle FL, Scratch(es), Polish




Bumper spoiler F, Scratch(es), Paint




Spare wheel compartment lining RR, Scratch(es), Repair/replace (lump sum)




Bumper moulding R, Scratch(es), Acceptable




Bumper R, Scratch(es), Polish




Tailgate / Boot, Scratch(es), Polish




ALPHABET

Historique Maintenance

Immatriculation: **GK-796-QR** Date de 1ère immatriculation: **21/11/2022**

Modèle: **Volkswagen T-ROC 1.0 TSI 110 LIFE BUSINESS VP [5P] bvm 6-110CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
17/09/2026	139.573	VGRF GRAND OUEST REZE	LIQUIDE DE FREIN
			REVISION
17/09/2026	139.573	VGRF GRAND OUEST REZE	Frais de participation à l'environnement
07/09/2026	138.389	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
25/03/2026	121.276	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
			GARDIENNAGE
			GARDIENNAGE
			PERMUTATIONS PNEUS
23/12/2025	118.850	VGRF GRAND OUEST	REVISION
			RECYCLAGE
23/10/2025	103.781	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
			GARDIENNAGE
04/04/2025	84.667	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
			GARDIENNAGE
26/03/2025	83.345	VGRF GRAND OUEST	BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			RECYCLAGE
			REVISION
31/10/2024	67.489	FLEET SOLUTIONS FRANCE	GARDIENNAGE
			PERMUTATIONS PNEUS
16/05/2024	53.837	VGRF GRAND OUEST	RECYCLAGE
			LIQUIDE LAVE GLACE
			LIQUIDE DE FREIN
			PLAQUETTES AR RPLT
			PLAQUETTES AV RPLT
			REVISION
22/04/2024	51.623	FLEET SOLUTIONS FRANCE	GARDIENNAGE
			REMPLACEMENT PNEUS ETE
			PERMUTATIONS PNEUS

Historique Maintenance

Immatriculation: **GK-796-QR** Date de 1ère immatriculation: **21/11/2022**

Modèle: **Volkswagen T-ROC 1.0 TSI 110 LIFE BUSINESS VP [5P] bvm 6-110CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
18/12/2023	38.647	NORAUTO SAS (PRODUIT SPE)	GARDIENNAGE
18/12/2023	38.646	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS ETE
01/09/2023	27.698	VGRF GRAND OUEST	LIQUIDE LAVE GLACE
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
			REVISION