



Citroen C4: P441VX

| | | | |
|-------------------------|--------------------------|-------------------------|--|
| Vinnumber: | VR7BCZKXCNE033976 | Versionname: | e-C4 100kW/50kWh Feel Pack automaat |
| First Registrationdate: | 30/06/2022 | Fiscalpower: | |
| Expertise Mileage: | 71371 | Power Kw: | 100 |
| Bodytype: | | Body colour: | Caramel Brown metaallak |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Electric | Parking lot: | 508 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | No | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Lining semi-leather |
| GPS | | Rear parking sensors |
| Autom climate control | | |
| Radio multimedia | | |

Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|------------------------------------|--------|----------|--------|
| Front | Left | 195 / 60 / 18 / 96 / H / Aluminium | 6,0 mm | Michelin | Summer |
| | Right | 195 / 60 / 18 / 96 / H / Aluminium | 5,2 mm | Michelin | Summer |
| Rear | Left | 195 / 60 / 18 / 96 / H / Aluminium | 6,1 mm | Michelin | Summer |
| | Right | 195 / 60 / 18 / 96 / H / Aluminium | 5,1 mm | Michelin | Summer |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 1 |

Interior, Stain, Cleaning



Wing FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Roof pillar L, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Wheel arch cover RR, Scratch(es), Replace



Door FR, Dent(s), Repair and paint (complete)



Mirror side repeater R, Broken, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Replace



Roof, Chemical pollution, Polish



| | |
|-----------------------|---|
| Kenteken | P441VX |
| Merk Model | Citroen e-C4 100kW/50kWh Feel Pack automaat |
| Brandstofsoort | Elektrisch |
| Datum deel1 | 30-06-22 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|---------------------------------|
| 17-06-26 | 70.897 | APK |
| 17-06-26 | 70.897 | Remklauw(en) achterzijde |
| 17-06-26 | 70.897 | Ruitenwischerblad(en) voorzijde |
| 04-09-25 | 60.686 | Onderhoudsbeurt |
| 04-09-25 | 60.686 | Remvloeistof |
| 04-09-25 | 60.686 | Tractie batterij lader |
| 03-10-24 | 42.330 | Onderhoudsbeurt |
| 31-08-23 | 21.045 | Onderhoudsbeurt |
| 02-03-23 | 13.135 | Onderhoudsbeurt |