



PEUGEOT 308 SW: GJ-756-EQ

Vinnumber:	VR3FCYHZTNY570931	Versionname:	PEUGEOT 308 SW BlueHDi 130 EAT8 ACTIVE PACK
First Registrationdate:	31/08/2022	Fiscalpower:	VP [5P] bva 8-130CH-7cv (break)
Expertise Mileage:	165945	Power Kw:	96
Bodytype:	Break	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

205/55/16/94 V			
Summer tyres:	Fr.L.	Bridgestone: 15%	Fr.R.
	Re.L.	Bridgestone: 15%	Re.R.
Tyre profile depth FL			7.3
Tyre profile depth FR			7.0
Tyre profile depth RL			7.3
Tyre profile depth RR			6.9
Tyre size FL			205/55 R 16 94 V
Tyre size FR			205/55 R 16 94 V
Tyre size RL			205/55 R 16 94 V
Tyre size RR			205/55 R 16 94 V
Tyre type FL			All seasons
Tyre type FR			All Seasons
Tyre type RL			All seasons
Tyre type RR			All Seasons
Tyre make FL			255
Tyre make FR			255
Tyre make RL			255
Tyre make RR			255

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Air vent RM, Broken, Replace



Interior, Stain, Cleaning



Steering wheel, Worn, Repair/replace (lump sum)



Wing FL, Scratch(es), Paint




Door FL, Dent(s), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Unclassped, Dismount/Mount



Wing RR, Dent(s), Repair and paint (complete)




Outer sill R, Dent(s), Replace and paint



Side repeater R, Broken, Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Deformed / Strained, Repair and paint (complete)



Bumper moulding R, Scratch(es), Replace



Historique Maintenance

Immatriculation: GJ-756-EQ Date de 1ère immatriculation: 31/08/2022

Modèle: Peugeot 308 SW BlueHDi 130 EAT8 ACTIVE PACK VP [5P] bva 8-130CH-7cv (break)

Date	Kilométrage	Fournisseur	Descriptif
01/04/2026	156.768	GERLERO	DIVERS ELEC
09/12/2025	140.302	GERLERO	RECYCLAGE
	0		REVISION
	0		DISQUES PLAQUETTES AV RPLT
	0		DIVERS CLIM
	0		FILTRE CLIM RPLT
	0		ADBLUE
08/04/2025	109.021	GERLERO	FILTRE A AIR RPLT
	0		REVISION
	0		FILTRE CLIM RPLT
	0		REVISION
	0		DIVERS CLIM
	0		COURROIE ACCESSOIRES RPLT
	0		ADBLUE
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		PILE DE CLE RPLT
	0		RECYCLAGE
30/09/2024	81.382	GERLERO	LIQUIDE DE FREIN
	0		PLAQUETTES AV RPLT
	0		ADBLUE
	0		RECYCLAGE
	0		REVISION
	0		FILTRE CLIM RPLT
07/03/2024	52.381	GERLERO	BALAIS ESSUIE GLACE AV
	0		ADBLUE
	0		REVISION
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
	0		REVISION
23/05/2023	28.814	HLC AUTOMOBILES	REVISION
	0		FILTRE CLIM RPLT