



SEAT Ibiza: 6370-MML

Vinnnumber:	VSSZZZKJ5RR021814	Versionname:	1.0 MPI 59kW (80CV) Reference XM berlina con portón 59kW 5P manual
First Registrationdate:	28/12/2023	Fiscalpower:	
Expertise Mileage:	90416	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Petrol		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	VS		
Registration Certificate Car (BE):	No		

Options


Number of keys total:	1	Radio
Number keys remote:	1	
Windows electric F:		
Cruise Control:		
Steering wheel multifunctional:		
Radio multimedia:		
Type of climate control:	Manual climate control	

Tyres

185/65/15/88 H				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				4.0
Tyre profile depth RR:				4.0
Tyre size FL:				185/65 R 15 88 H
Tyre size FR:				185/65 R 15 88 H
Tyre size RL:				185/65 R 15 88 H
Tyre size RR:				185/65 R 15 88 H
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				259
Tyre make FR:				259
Tyre make RL:				259
Tyre make RR:				259

Assistance equipment

Repair kit:	No
Interior, Dirty, Cleaning	





Ignition key, Missing, Repair/replace (lump sum)



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Tyre repair kit, Missing, Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Dent(s), Repair and paint (complete)



Tyres, No damage, Check





Bodywork, Glue residues, Remove lettering



Fuel cap cover, Scratch(es), Paint

