



Volkswagen ID.5 BEV 174pk 77kWh Pro Style Multimedia Comfort, Aug-22, 185,275 km



Memo



VIN	WVGZZZE2ZNP506015
Initial registration	26-08-2022
Initial Dutch Registration	26-08-2022
European Type Approval	e1*2018/858*00004*08
Mileage reading / hour counter reading	185,275 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	2017 kg
Doors	5
Power capacity	128 kW
Emission code / Energy label	Z
Wheelbase	277
Loading space	
Load capacity	
RDW details	
Battery capacity	77 kWh
Range	534 km
Battery health	
Charging cables type	2
AC/DC	ACDC
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Gray
Country of registration	The Netherlands
Origin	Lease

Accessories fitted to vehicles

 Rear view camera	 Central locking remote control	 Navigation
 Adaptive cruise control	 Cruise control	 Parking sensors rear
 Adaptive power steering	 Electronic Stability Program	 Parking sensors front + rear
 ABS	 Electric windows front	 Start immobiliser
 Automatic air conditioning ECC	 Electric windows front + rear	 Fold away towbar
 Automatic interior mirror dimmer	 LED lighting	 Heated front seats
 Bluetooth telephone connection	 Alloy rims	 Heat reflecting glass

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|-----------------------------|-----------------------------|-----------------------------|
| • AEB | • Forward Collision Warning | • Multifunctioneel stuur |
| • Afwijk. dakkleur | • Geluidsimulator | • Multimedia-voorbereiding |
| • Apple CarPl./Android Auto | • Geluidsisolerend glas | • Oplaadmogelijkheid |
| • Armsteun voor | • Hoofd airbag(s) a. | • Passagiersairbag |
| • Band.sp.contr.syst. | • Hoofd airbag(s) v. | • Rijstrooksensor met corr. |
| • Bestuurdersairbag | • In delen neerkl. achterb. | • Sfeerverlichting |
| • Bluetooth telefoonvoorb. | • Interieur voorverwarming | • Spraakbediening |
| • Buitensp. elekt. inklapb. | • Keyless start | • Stoel best. hoogte verst. |
| • Buitensp. elektr. + verw. | • LED achterlichten | • Verkeersbord detectie |
| • Centrale airbag v. | • LED dagrijverlichting | • Vermoeidheids herkenning |
| • Connected services | • LED koplampen | • Voll. dig. instr. paneel |
| • DAB radio | • Lichtmetalen velgen 19" | • Zij airbag(s) v. |
| • ESP | • Luxe interieur afwerking | |



Comments

No remarks

Vehicle state

MOT due date	26-08-2026	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location	Wheel locks	Not present
			Owner		



Tyres

Rim size	19"		
Wheel	Brand	Type	Tread depth
Front wheel left	Continental	Summer tyre	3 mm
Front wheel right	Continental	Summer tyre	3 mm
Rear wheel left	Continental	Summer tyre	4 mm
Rear wheel right	Continental	Summer tyre	5 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection

Incident	Component	Observations
----------	-----------	--------------

Unacceptable damage

1		Bekl zitting v l	worn
2		Rear wing left	dent(s)
3		Bumper v bekleding	scratch(es)
4		Buitenspiegel r kap	scratch(es)
5		Deur a r sierlijst	scratch(es)
6		Dorpel r bekleding buiten	scratch(es)
7		Rear bumper	scratch(es)
8		Reflector	Gebroken

9		Rear bumper	scratch(es)
10		Boot space upholstery	scratch(es)
11		Boot space upholstery	scratch(es)
12		Kofferklep spoiler	scratch(es)
13		Roof	various damage (see photo)
Comments No remarks			

Vendor