


2-FHA-990

2-FHA-990 · ST Line 1.0i EcoBoost 125pk M6 · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FHA-990	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF02XXERK2RG48550
Model	Puma	Cylinder Capacity	999 ^{cm3}
Model Versions	ST Line 1.0i EcoBoost 125pk M6	Transmission Type	Handmatig geschakelde transmissie
		First Admission	07-05-2024
Body Type	5 door hatchback	Odometer	60.987 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	92		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Navigation system

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior

Adequate

Maintenance Remarks

Motorolie verversen

Condition interior

Adequate

Previous Repairs


Unknown

Last Maintenance Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	5 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	3 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	5 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Small scratch(es)

Touch-up / Polish

No



Damage Part

Damage Type

Repair Type


Acceptable

Frontdoor – Right

Small scratch(es)

Acceptable

Yes



Damage Part

Damage Type

Notes

Repair Type

Acceptable


Roof

Small dent(s)

Dakstijl

Panelbeating & Spray

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Bumper – Front

Dent(s)

En ontzet

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Left

Small dent(s)

Restyle

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Rear

Small scratch(es)

Acceptable

Yes



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Skirt - Right

Dislocated / Loose

Rubber

Repair

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable


Skirt - Left

Dislocated / Loose

Rubber

Repair

No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Handgrip	Replace	No