MACADAM











Mercedes GLC-Klasse (KKL): 2BPE228

Vinnumber:	**W1N2539111V327198**	Versionname:	**GLC300de Business Solution 2.0d 306pk/cv 5p 4Matic 9G-Tronic**
First Registrationdate:	**2/02/2022**	Fiscalpower:	
Expertise Mileage:	**134144**	Power Kw:	**143**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Diesel**		
Maintenance	**NOT OK**		
Maintenance	**met 2000 km overschreden**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**235/55/19/105 V**			
	Fr.L.	**Michelin: 2 mm**	Fr.R.	**Michelin: 2 mm**
	Re.L.	**Michelin: 3 mm**	Re.R.	**Michelin: 3 mm**

Tyre profile depth FL	**2.0**
Tyre profile depth FR	**2.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**235/55 R 19 105 V**
Tyre size FR	**235/55 R 19 105 V**
Tyre size RL	**235/55 R 19 105 V**
Tyre size RR	**235/55 R 19 105 V**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**2**		
Number of charging cables (rapid charge)	**1**		

Service, Maintenance, Check



Windscreen, Stone chip(s), Acceptable




Bonnet, Stone chip(s), Acceptable






Bumper F, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable






Door RL, Scratch(es), Acceptable








Wing RL, Scratch(es), Acceptable






Alloy rim FL polished, Scratch(es), Repair and paint (complete)







Alloy rim RL polished, Scratch(es), Repair and paint (complete)






Tailgate / Boot, Scratch(es), Acceptable




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)





Door FR, Repaired, Check







Door RR, Repaired, Check





Wing FR, Repaired, Check




Alloy rim RR polished, Scratch(es), Acceptable





Alloy rim FR polished, Scratch(es), Repair and paint (complete)









Onderhoudshistorie van: W1N2539111V327198

ALPHABET

Kenteken	2BPE228
Merk Model	Mercedes GLC300de Business Solution 2.0d 306pk/cv 5p 4Matic 9GTronic
Brandstofsoort	Diesel
Datum deel1	2/2/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/19/25	107,182	mercedes assyst b	Uitvoeren
11/19/25	107,182	ruitenwisserrubber achter	Vervangen
11/19/25	107,182	ruitenwisserrubber vooraan	Vervangen
12/13/24	80,021	brandstoffilter	Vervangen
12/13/24	80,021	klein materiaal	
12/13/24	80,021	luchtfilter	Vervangen
12/13/24	80,021	mercedes assyst a	Uitvoeren
12/13/24	80,021	remvloeistof	Vervangen
12/13/24	80,021	ruitenwisserrubber achter	Vervangen
12/13/24	80,021	ruitenwisserrubber vooraan	Vervangen
1/16/24	52,780	klein materiaal	Uitvoeren
1/16/24	52,780	mercedes assyst b	Uitvoeren
1/16/24	52,780	ruitenwisserrubber achter	Vervangen
1/16/24	52,780	ruitenwisserrubber vooraan	Vervangen
1/16/24	52,780	schuif/ -kanteldak	Smeren
1/16/24	52,780	stoffilter (motor compartiment)	Vervangen
1/11/23	28,182	mercedes assyst a	Uitvoeren