



CITROËN C3: 5607-MCG

Vinnumber:	VF75XYHTUNT624041	Versionname:	Citroen BlueHDi 75KW (100CV) S&S Feel Pack berlina con portón 75kW 5P manual
First Registrationdate:	16/11/2022	Fiscalpower:	
Expertise Mileage:	143937	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Luggage cover
Number keys remote	2	
GPS big screen color		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

205/55/16/94 V				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes
Boot lid covering R, Scratch(es), Acceptable	



Interior, Dirty, Cleaning



Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Interior, Damaged, Check



Door RL, Scratch(es), Acceptable




Door FL, Scratch(es), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Windscreen, Broken, Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Headlight R, Scratch(es), Polish



Wing FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

