VEHICLE REPORT

IT · 05/11/2026
2026-11-05 11:47

VIN: Targa: Merchant:

VEHICLE DETAILS

Targa		First Registration	**2022-03-02**
Marca	N/A	Mileage	N/A
Modello e Allestimento		Keys	N/A
VIN		Owners	**2**
Merchant		Seats	**5**
Branch		Previous Use	**AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE**
KW	**143**	VAT	N/A
CC	**0**	Country	**IT**
Fuel	**GASOL-ELETTR**	Euro	**EURO6**
GPL	**Non presente**	Cambio	**Non presente**
Gancio	N/A		

CAR PHOTOS (69)


Front


Front left


Front


Front left


Rear


Rear


Rear


Tailgate


Trunk


Roof.


Interior rear


Interior rear


Interior rear


Interior front


Roof.


Interior front


Interior front.


Interior rear


Interior rear


Center console and dashboard


Navigation on.


Speedometer with started engine.


Roof.


Roof.


Roof.


Engine compartment


Engine compartment


Interior front.


Front door left


Left side front


Engine compartment


Left side front


Rear door left


Trunk


Front left


Front door left



Front door left



Rear



Rear fender left



Left side front



Front fender left




Left side rear



Rear



Left side front



Front left



Front left



Front left



Front fender right



Rear fender left



Front fender left



Front fender left



Front fender left



Rear fender left



Rear fender left



Left side rear



Left side rear



Rear fender left



Rear fender left



Additional photos (optional)



Additional photos (optional)



Left side rear



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)

CARFAX **Vehicle History Report**

MERCEDES GLE 350 de 4MATIC

Vehicle reference:
W1N1671171A621606

Body type:
Estate

Engine size:
1950 cm³

Total system power:
143 kW / 194 hp

Combustion engine power:
143 kW / 194 hp

Gearbox type:
Automatic

Hybrid vehicle:
Electric, Diesel

Quick check

Damage
This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

Import
Not a private import

Legend


- No issues reported or indicated
- Valuable Information
- Requires attention
- Data unavailable

Damage overview

05/2024

Affected area (3):

Location reference, does not indicate the extent of the damage.



- Left
- Left front
- Left rear

Reported in

Italy

Damage type/cause

Collision with another vehicle

Damage severity:

Minor to Moderate

Mostly cosmetic damage, such as dents or scratches. Some components may have additional damage, but vehicle operation and safety are generally not impacted.

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

Recommended maintenance

Default schedule
Provided by CARFAX Europe

Vehicle age
4 years, 8 months

Maintenance due so far

These service tasks are expected based on the vehicle age. Verify if they were completed.

Before buying, ask the seller:
- Are service records available?
- Were the following services performed?

Engine oil and oil filter **due 4 times**
Change every year

Brake fluid **due 2 times**
Change every 2 years

Costly upcoming service tasks

Before buying, confirm whether:
- Any of the upcoming maintenance tasks are already completed.
- You've accounted for related costs in your future budget.

Brake discs and pads
Inspect yearly, replace as needed

Tires
Inspect yearly, replace as needed

CARFAX tips



Keeping up with scheduled servicing is a strong indicator that the vehicle has been well cared for and is in good overall condition.

Mileage Check

No issues reported

According to the data provided to CARFAX, there are no indications of odometer manipulation.

Last odometer reading

46 312 km

Reported on: 2024-05-03

Date	Mileage
05/2024	46 312 km



CARFAX tips



Mileage can have a significant impact on a vehicle's value.

Consider whether the mileage matches what you'd expect for the vehicle. Look for signs of wear, compare the readings with typical yearly averages.

Owners BETA



Owner(s) in Italy

Purchase year:
2022

Damage reported on:
05/2024

Technical details

Engine and performance

Hybrid vehicle
Electric, Diesel

Combustion engine power
143 kW / 194 hp

Electric engine power
Not available

Total system power
143 kW / 194 hp

Environment and consumption

EU emission standard
Euro 6

Weight

Curb weight
2 655 kg

Max payload
605 kg

Gross vehicle weight
3 260 kg

Dimensions

Length
4 954 mm

Width
2 022 mm

Wheelbase
2 995 mm

Other information

European vehicle category
M1

EU standard code
e1*2007/46*1885*14

Number of doors
5

Number of seats
5

History information

Date	Mileage	Event
2022-03-02		**Registered in Italy**
05/2024	46 312 km	**Damage reported in Italy**

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our Terms and conditions.