MACADAM










Ford Mustang: N223KS

Vinnumber:	**WF0TK1E73MMA38386**	Versionname:	**Mustang Mach-E 210kW/ 98,8kWh Extended RWD automaat**
First Registrationdate:	**8/11/2021**	Fiscalpower:	
Expertise Mileage:	**94230**	Power Kw:	**210**
Bodytype:		Body colour	**Premium Metaallak: Carbonized Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**628**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining leather	
GPS		Rear parking sensors	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 104 / W / Aluminium	5,0 mm	Goodyear	All season
	Right	225 / 60 / 18 / 104 / W / Aluminium	5,2 mm	Goodyear	All season
Rear	Left	225 / 60 / 18 / 104 / W / Aluminium	4,3 mm	Goodyear	All season
	Right	225 / 60 / 18 / 104 / W / Aluminium	3,1 mm	Goodyear	All season

Assistance equipment

Number of charging cables (rapid charge)	**1**

Outside rear-view mirror housing L, Broken, Replace and paint




Door RL, Bad repair, Repair and paint (complete)





Windscreen, Stone chip(s), Windscreen repair




Door RR, Scratch(es), Repair and paint (complete)




Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Bumper R, Scratch(es), Repair and paint (complete)





Onderhoudshistorie van: WF0TK1E73MMA38386

ALPHABET

Kenteken	N223KS
Merk Model	Ford Mustang Mach-E 216kW/ 98,8kWh Extended RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	11/8/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/1/25	75,689	APK
1/20/25	64,871	Onderhoudsbeurt
1/20/25	64,871	Remvloeistof
1/20/25	64,871	Ruitenwisserblad(en) voorzijde
1/16/24	46,514	Vervanging band
4/4/23	32,474	Onderhoudsbeurt
5/19/22	11,994	Reparatie band(en)