



SKODA Karoq: 3234-MGH

Vinnumber:	TMBLJ7NU4P5052260	Versionname:	2.0 TDI 110kW (150CV) DSG 4X4 Ambition todoterreno 110kW 5P automática
First Registrationdate:	24/04/2023	Fiscalpower:	
Expertise Mileage:	152237	Power Kw:	
Bodytype:	SUV	Body colour	White
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		Roof bar alu
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	215/60/16/99 V			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/60 R 16 99 V
Tyre size FR				215/60 R 16 99 V
Tyre size RL				215/60 R 16 99 V
Tyre size RR				215/60 R 16 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	No
------------	-----------

Registration document, Missing, Repair/replace (lump sum)



Boot lid covering R, Hole, Replace



Boot lid covering R, Scratch(es), Replace




Boot lid covering R, Scratch(es), Replace



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)



Grille frame, Broken, Replace



Windscreen, Broken, Replace



Tyre repair kit, Missing, Repair/replace (lump sum)



Tyres, No damage, Check

