MACADAM










Polestar 2: R350DD

Vinnumber:	**LPSVSEGEKNL082931**	Versionname:	**Polestar 2 170kW/ 78kWh Single Motor Long Range**
First Registrationdate:	**23/08/2022**	Fiscalpower:	
Expertise Mileage:	**132608**	Power Kw:	**170**
Bodytype:		Body colour	**Void**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**1033**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Rear parking sensors	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / V / Aluminium	3,8 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / V / Aluminium	3,6 mm	Michelin	Summer
Rear	Left	245 / 45 / 19 / 102 / V / Aluminium	6,0 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / V / Aluminium	5,8 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Service, Maintenance, Execute



Wing FL, Chemical polution, Repair and paint (complete)




Door FL, Scratch(es), Repair and paint (complete)




Wing RL, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)







Bumper trim F, Scratch(es), Replace





Bonnet, Stone chip(s), Repair and paint (complete)




Wing RR, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)









Tailgate / Boot, Dent(s), Repair and paint (complete)





Onderhoudshistorie van: LPSVSEGEKNL082931

ALPHABET

Kenteken	R350DD
Merk Model	Polestar Polestar 2 170kW/ 78kWh Single Motor Long Range
Brandstofsoort	Elektrisch
Datum deel1	8/23/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
8/18/26	127,758	APK
9/25/25	103,176	Onderhoudsbeurt
9/25/25	103,176	Remvloeistof
9/25/25	103,176	Ruitenwisserblad(en) voorzijde
11/14/24	78,317	Onderhoudsbeurt
11/14/24	78,317	Ruitenwisserblad(en) voorzijde
11/14/24	78,317	Sleutelbatterij