



### RENAULT TRAFIC:

Vinnumber:	<b>VF1FL000X64346803</b>	Versionname:	<b>L2H1 dCi 120 Grand Confort 2.9T</b>
First Registrationdate:	<b>29/01/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>84705</b>	Power Kw:	<b>88</b>
Bodytype:		Body colour:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Steel</b>
Transmission:		Parking lot:	<b>Icv09</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Steel</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Light Commercial Vehicle</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

### Options

Number of keys total	<b>1</b>	Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

### Limited Technical Inspection

### Tyres

205/65/16/92 H				
Summer tyres:	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/65 R 16 92 H</b>
Tyre size FR				<b>205/65 R 16 92 H</b>
Tyre size RL				<b>205/65 R 16 92 H</b>
Tyre size RR				<b>205/65 R 16 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>2480</b>
Tyre make FR				<b>2480</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

### Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>3431,93</b>
Ignition key, Missing, Replace	<b>262,56</b>



Seat cover FL, Stain, Cleaning 29,16



Seat cover FR, Stain, Cleaning 29,16



Bumper spoiler F, Scratch(es), Replace 123,93



Bumper F, Scratch(es), Repair and paint (complete) 222,43



Wing RL, Dent(s) and scratch(es), Repair and paint (complete) 383,19



Wing trim RL, Scratch(es), Replace 100,69



Door FL, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Smart repair 116,69



Wheel cover FL, Scratch(es), Replace 44,82



Bumper R, Scratch(es), Smart repair 116,69



Boot moulding, Scratch(es), Acceptable 0,00



Boot door panel RR, Dent(s), Acceptable 0,00



Boot door panel RL, Dent(s), Acceptable 0,00



Wheel cover FR, Scratch(es), Replace 44,82



Wing FR, Scratch(es), Repair and paint (complete) 231,22



Door FR, Scratch(es), Repair and paint (complete) 334,34



Outside rear-view mirror housing R, Scratch(es), Smart repair 116,69



Central pillar R, Scratch(es), Repair and paint (complete) 513,19



Door RR, Dent(s) and scratch(es), Repair and paint (complete) 393,85



Wing RR, Dent(s) and scratch(es), Repair and paint (complete) 323,68



Wheel cover RR, Scratch(es), Replace

44,82

