



## Peugeot 3008 (UKL): 2AFB310

|                                   |                          |                        |                                                      |
|-----------------------------------|--------------------------|------------------------|------------------------------------------------------|
| Vinnnumber:                       | <b>VF3M45GFUMS079284</b> | Versionname:           | <b>3008 GT 1.6 PureTech S&amp;S 180pk/cv 5p EAT8</b> |
| First Registrationdate:           | <b>15/03/2021</b>        | Fiscalpower:           |                                                      |
| Expertise Mileage:                | <b>179455</b>            | Power Kw:              | <b>133</b>                                           |
| Bodytype:                         |                          | Type of rims (mounted) | <b>Aluminium</b>                                     |
| Gearbox:                          | <b>Automatic</b>         |                        |                                                      |
| Transmission:                     |                          |                        |                                                      |
| Fueltype:                         |                          |                        |                                                      |
| Maintenance                       | <b>OK</b>                |                        |                                                      |
| Maintenance                       | <b>dans 29300 km</b>     |                        |                                                      |
| Battery functioning               | <b>Yes</b>               |                        |                                                      |
| Type of rims (mounted)            | <b>Aluminium</b>         |                        |                                                      |
| Certificate of Conformity         | <b>Yes</b>               |                        |                                                      |
| Category                          | <b>Passenger Car</b>     |                        |                                                      |
| Registration Certificate Car (BE) | <b>Yes</b>               |                        |                                                      |

## Options

|                          |                            |                 |                      |
|--------------------------|----------------------------|-----------------|----------------------|
| Number of keys total     | <b>2</b>                   | Luggage cover   |                      |
| GPS                      |                            | Type of Tow bar | <b>Tow bar fixed</b> |
| Type of Maintenance book | <b>Digital maintenance</b> |                 |                      |
| Type of GPS storage      | <b>HD</b>                  |                 |                      |

## Tyres

|                       |                   |                |       |                |
|-----------------------|-------------------|----------------|-------|----------------|
|                       | 225/55/18/102 V   |                |       |                |
| Summer tyres:         | Fr.L.             | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
|                       | Re.L.             | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |
| Tyre profile depth FL | 5.0               |                |       |                |
| Tyre profile depth FR | 5.0               |                |       |                |
| Tyre profile depth RL | 6.0               |                |       |                |
| Tyre profile depth RR | 6.0               |                |       |                |
| Tyre size FL          | 225/55 R 18 102 V |                |       |                |
| Tyre size FR          | 225/55 R 18 102 V |                |       |                |
| Tyre size RL          | 225/55 R 18 102 V |                |       |                |
| Tyre size RR          | 225/55 R 18 102 V |                |       |                |
| Tyre type FL          | Summer            |                |       |                |
| Tyre type FR          | Summer            |                |       |                |
| Tyre type RL          | Summer            |                |       |                |
| Tyre type RR          | Summer            |                |       |                |
| Tyre make FL          | 259               |                |       |                |
| Tyre make FR          | 259               |                |       |                |
| Tyre make RL          | 259               |                |       |                |
| Tyre make RR          | 259               |                |       |                |

## Assistance equipment

|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

Seat cover FL, Worn, Acceptable



Bumper spoiler F, Deformed / Strained, Replace



Bumper moulding F, Scratch(es), Replace



Bumper F, Scratch(es), Spot repair



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door FL, Dent(s), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Bumper R, Scratch(es), Replace



Wing RR, Dent(s), Acceptable



Door RR, Dent(s), Paintless dent repair



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door FR, Bad repair, Repair and paint (complete)



|                       |                                                   |
|-----------------------|---------------------------------------------------|
| <b>Kenteken</b>       | 2AFB310                                           |
| <b>Merk Model</b>     | Peugeot 3008 GT 1.6 PureTech S&S 180pk/cv 5p EAT8 |
| <b>Brandstofsoort</b> | Benzine                                           |
| <b>Datum deel1</b>    | 3/15/21                                           |

| Datum reparatie | Kilometerstand | Reparatie omschrijving      | Bewerking |
|-----------------|----------------|-----------------------------|-----------|
| 9/30/25         | 149,604        | luchtfILTER interieur       | Vervangen |
| 9/30/25         | 149,604        | oliezeef                    | Vervangen |
| 9/30/25         | 149,604        | remblokken vooraan          | Vervangen |
| 9/30/25         | 149,604        | remvloeistof                | Vervangen |
| 2/6/25          | 127,560        | diagnose                    | Uitvoeren |
| 2/6/25          | 127,560        | nazicht technische keuring  | Uitvoeren |
| 12/2/24         | 119,362        | 120000 km                   | Uitvoeren |
| 12/2/24         | 119,362        | bougie                      | Vervangen |
| 12/2/24         | 119,362        | luchtfILTER                 | Vervangen |
| 12/2/24         | 119,362        | luchtfILTER interieur       | Vervangen |
| 12/2/24         | 119,362        | oliezeef                    | Vervangen |
| 12/2/24         | 119,362        | remblokken achter           | Vervangen |
| 12/2/24         | 119,362        | ruitenswisserrubber achter  | Vervangen |
| 12/2/24         | 119,362        | ruitenswisserrubber vooraan | Vervangen |
| 12/7/23         | 89,793         | 90000 km                    | Uitvoeren |
| 12/7/23         | 89,793         | luchtfILTER interieur       | Vervangen |
| 12/7/23         | 89,793         | oliezeef                    | Vervangen |
| 8/29/23         | 81,816         | diagnose                    | Uitvoeren |
| 8/29/23         | 81,816         | klepdeksel                  | Vervangen |
| 2/28/23         | 60,381         | ruitenswisserrubber vooraan | Vervangen |
| 2/14/23         | 59,276         | 60000 km                    | Uitvoeren |
| 2/14/23         | 59,276         | bougie                      | Vervangen |
| 2/14/23         | 59,276         | luchtfILTER                 | Vervangen |
| 2/14/23         | 59,276         | luchtfILTER interieur       | Vervangen |
| 2/14/23         | 59,276         | oliezeef                    | Vervangen |
| 2/14/23         | 59,276         | remvloeistof                | Vervangen |
| 1/31/22         | 30,371         | 30000 km                    | Uitvoeren |
| 1/31/22         | 30,371         | oliezeef                    | Vervangen |
| 11/5/21         | 24,459         | controle niveaus            | Uitvoeren |