



RENAULT EXPRESS: 2815-MFL

Vinnumber:	VF1RJK00870135851	Versionname:	Confort 1.5 Blue dCi 55 kW (75 cv) furgón derivado de turismo 55kW 4P manual
First Registrationdate:	13/03/2023	Fiscalpower:	
Expertise Mileage:	55268	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	1	Radio:	
Number keys remote:	1		
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

185/65/15/88 H				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Kumho: 5 mm	Re.R.	Kumho: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				2482
Tyre make RR				2482

Assistance equipment

Repair kit:	No
-------------	-----------

Interior, Dirty, Cleaning



Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Door panel RR, Scratch(es), Replace



Interior, Damaged, Replace



Boot lid covering R, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover FL, Missing, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RL, Scratch(es), Paint



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Scratch(es), Paint



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Tyre repair kit, Missing, Repair/replace (lump sum)



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Broken, Replace



Rear panel, Dent(s) and scratch(es), Repair and paint (complete)



Internal boot lining L, Scratch(es), Replace



Boot moulding, Broken, Replace



Boot door panel RR, Scratch(es), Paint



Tyres, No damage, Check

