



Expertise

Protocol number: 46030930
Order No. / Reference: 26497537
Inspection date: 17 Jun 2026

Manufacturer: Volkswagen

Model: ID. Buzz Pro

VIN: WV2ZZZEB8PH011708



Vehicle details

Manufacturer / Type / Model / Equipment

Volkswagen ID. Buzz Pro

Vehicle Identification number WV2ZZZEB8PH011708

Mileage (Read) 41,392 km

First registration 23 Dec 2022

Number of holders 1

Power / Engine displacement 70 kw /

Fuel type / Cylinder Electric / 0

Gearbox / Number of gears Direct drive / 1

Type of drive Rear drive

Type of vehicle Van

Colour / colour code Candy-Weiß/Limonengelb
Metallic

Doors / Seats 5 / 5

Upholstery type Cloth

Colour of upholstery Black-Grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	233 Tag(e)
Last service on / at	02/2025 at 29,773 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP936466
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CQY 00010		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	3,000 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105T	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	255/50 R19 107T	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103T	Winter tyres on Light alloy	Goodyear	7mm / 7mm
2)	255/55 R18 105T	Winter tyres on Light alloy	Goodyear	8mm / 8mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS
- Airbag: Head airbags for the outer rear seats
- Armrests for front seats (inside)
- Evasive steering assist and turn assist
- Exterior mirrors, driver's side convex, passenger's side convex
- Battery (58 Ah/340 A)
- Operating voltage 12 V
- third brake light
- DC/DC converter 3.0 KW
- Three-point automatic seat belts, rear outer seats, with ECE label
- e-Sound
- Single-tone signal horn
- Window: Glass tinted dark in the background
- Window: Fixed side window in the passenger compartment, front left
- Electric windows, front
- luggage compartment cover
- Cruise control system with speed limiter
- Tailgate with window cutout
- Heated rear window
- Interior lighting in the front and rear footwells
- Air conditioning system "Air Care Climatronic" with active combination filter
- Mode 3 Type 2 charging cable, 16 A
- LED taillights
- Steering wheel: Multifunction steering wheel
- Multifunctional camera
- Non-smoking version
- eCall emergency call system
- Proactive occupant protection system (PreCrash Basic and Front)
- Radio: Diversity antenna for FM reception
- Radio accessories: 2 USB-C ports in the instrument panel and 1 USB-C charging port in the front.
- Wheels/Tires: "Tilburg" alloy wheels 8 J x 19 front, 9 J x 19 rear, in black, diamond-turned finish
- Rear seat bench and backrest can be folded down in a split configuration
- Sliding door, on the right in the passenger/cargo area
- Speed-sensitive power steering (Servotronic)
- dimmable interior safety mirror
- Sun visors with mirrors, illuminated
- Bumpers in body color
- Phone: Car2X
- Ambient lighting with logo projection
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: "Discover Pro" navigation function
- Airbag for driver and front passenger
- Airbag: Side and head airbags for driver and front passenger
- Electrically adjustable, folding and heated exterior mirrors, with passenger-side mirror lowering function.
- Exterior mirror housings in high-gloss black and door handles in body color
- Vehicle tool kit
- CCS charging socket
- Design badges D-pillar
- Three-point automatic seat belts at the front with belt and end fitting tensioners and height adjustment
- Parking assistance in the front and rear areas
- Electronic Stability Program
- Window: Rear window
- Window: Fixed side window in the passenger compartment, front right
- Windscreen in heat-insulating glass
- Total weight: Permissible total weight 3,000 kg
- Transmission: Direct drive, 1-speed
- Tailgate closing without interior unlocking function
- Rear window wiper/washer system with intermittent function
- Headrests (5)
- Paint finish: Metallic - Monosilver
- LED luggage compartment lighting
- LED headlights
- Headlight range control
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Upholstery: Cloth
- Radio: App-Connect incl. App-Connect Wireless
- Radio: Digital radio reception (DAB+)
- Radio: "Ready 2 Discover" radio with 25.4 cm (10-inch) color touchscreen
- Wheels, tires: Covers for alloy wheels
- Wheels/Tires: Tire pressure monitoring system
- Wheels/Tires: Wheel bolts with enhanced theft protection
- Windscreen wiper intermittent control
- Sliding door, left side in the passenger/cargo area
- Keys for locking system: 2 vehicle keys
- Seatbelt check
- Seats: Height adjustment for both front seats, manual
- Lane keeping assistant "Lane Assist"
- LED daytime running lights
- Telephone: Mobile phone interface with inductive charging function
- Traffic sign recognition
- Electronic immobilizer
- Central locking with keyless start system "Keyless Start" without safe locking



Extra equipment

- Towbar, foldable (with electric release)
- Mains charging cable for household socket (Mode 2 Type 2, 10A)
- Package: Infotainment package (voice control - "Discover Pro" navigation system - 9 speakers (5 front speakers and 4 rear speakers) - "Comfort" mobile phone interface with inductive charging function)
- Package: Open & Close Package "Plus" (illuminated door handle recesses - central locking with keyless locking and starting system "Keyless Advanced" with safe locking - electric tailgate (opening and closing) with "Easy Open" and "Easy Close" function - electric sliding door left - electric sliding door right - anti-theft alarm system with interior monitoring, backup horn and tow-away protection - rear approach lighting)
- Paint finish: Solid/Metallic (two-tone)
- Package: Comfort Package (ID. Buzz Box, removable center console with storage compartments between the front seats - 2 USB-C interfaces in the instrument panel, USB-C charging ports front and rear - Multifunction steering wheel in synthetic leather, with touch controls, heated - Heated seats for both seats in the driver's cab, separately adjustable left and right - Heated windshield in heat-insulating glass - Automatically dimming rearview mirror - Intermittent windshield wipers with rain sensor - Heated windshield washer nozzles, front)
- Wheels/Tires: 19" "Venlo" alloy wheels (4 "Venlo" alloy wheels 8 J x 19 front, 9 J x 19 rear, in silver, with black plastic trim - covers for alloy wheels - Airstop tires 235/55 R 19 105 T front, Airstop tires 255/50 R 19 107 T rear)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Bonnet	Handle - engine hood release cable - Differs from the original configuration - Perform diagnosis
2	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
3	Trim / covers	Boot lid - interior trim - Scratch(es) - Replace
4	Trim / covers	Roof lining - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - No deduction
2	Mudguard - right side	Mudguard - right side - Scratch(es) - No deduction
3	Trim / covers	Cargo area - lining - right side - Scratch(es) - No deduction
4	Trim / covers	Cargo area - lining -left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Damage 1: Bonnet: Handle - engine hood release cable - Differs from the original configuration - Perform diagnosis




Damage 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 3: Trim / covers: Boot lid - interior trim - Scratch(es) - Replace



Damage 3: Trim / covers: Boot lid - interior trim - Scratch(es) - Replace



Damage 4: Trim / covers: Roof lining - Broken / torn - Replace



Damage 4: Trim / covers: Roof lining - Broken / torn - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WV2ZZZEB8PH011708
Hersteller / Modell: VOLKSWAGEN VW ID. Buzz

Datum	KM-Stand	Beschreibung
06.02.2025	29.773	Bremsflüssigkeit ern; Regelwartungsdienst; Reparatur Sonstiges