

Inspection data

Inspection date **06/05/2026 11:40**

Vehicle data

License plate

Make / Type **SKODA ENYAQ IV**


VIN **TMBJB7NY1NF034698**

First registration date **19/04/2022**

Mileage **92.963 km**



Vehicle pictures





Tires

Location	Position	Depth	Dimension	Make	Type
Voor	Links	6,0 mm	235/50 R 20 104 T	Goodyear	Winter
Voor	Rechts	7,0 mm	235/50 R 20 104 T	Goodyear	Winter
Achter	Links	6,0 mm	235/50 R 20 104 T	Goodyear	Winter
Achter	Rechts	4,0 mm	235/50 R 20 104 T	Goodyear	Winter

Damages with pictures

Claim(s) own risk to be invoiced

Carrosserie

Dak

Hagelschade


PDR - Uitdeuken z. schilderen (hagelschade)



Dakstijl R

Hagelschade

PDR - Uitdeuken z. schilderen (hagelschade)



Dakstijl L

Hagelschade

PDR - Uitdeuken z. schilderen (hagelschade)



Not invoiced

Bumper V

Kras(sen)

LI - Herstellen en schilderen (compleet)

