



Skoda Enyaq (KKL): 2CAH430

Vinnumber:	TMBJC7NY6NF039179	Versionname:	Enyaq iV 80 204pk/cv 5p
First Registrationdate:	10/05/2022	Fiscalpower:	
Expertise Mileage:	79578	Power Kw:	69
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Electric		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/45/21/104 T			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				235/45 R 21 104 T
Tyre size FR				235/45 R 21 104 T
Tyre size RL				255/40 R 21 102 T
Tyre size RR				255/40 R 21 102 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Engine insulation, Damaged, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Replace



Charging cable (normal), Missing, Check



Rubber seal for boot lid, Broken, Replace



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Kenteken	2CAH430
Merk Model	Skoda Enyaq iV 80 204pk/cv 5p
Brandstofsoort	Elektrisch
Datum deel1	5/10/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/20/26	71,676	diagnose	Uitvoeren
4/27/26	70,577	diagnose	Uitvoeren
4/27/26	70,577	klein materiaal	
4/27/26	70,577	luchtfILTER interieur	Vervangen
4/27/26	70,577	Onderhoudsbeurt (variabel interval)	Uitvoeren
4/27/26	70,577	remvloeistof	Vervangen
4/27/26	70,577	ruitenwisservloeistof	Bijvullen/-laden
6/6/24	28,513	klein materiaal	Uitvoeren
6/6/24	28,513	luchtfILTER interieur	Vervangen
6/6/24	28,513	Onderhoudsbeurt (variabel interval)	Uitvoeren
6/6/24	28,513	remvloeistof	Vervangen