MACADAM










PEUGEOT PARTNER: FZ-247-RZ

Vinnumber:	**VR3EFYHYCMN505581**	Versionname:	**PEUGEOT PARTNER BHDI 100 S&S 100 S&S 1000KG STD ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**2/06/2021**	Fiscalpower:	
Expertise Mileage:	**70205**	Power Kw:	**75**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Rear parking sensors	
GPS big screen color		Sliding door right-side	
Windows electric F		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**205/60/16/96 V**			
	Fr.L.	**Bridgestone: 85%**	Fr.R.	**Bridgestone: 75%**
	Re.L.	**Bridgestone: 60%**	Re.R.	**Bridgestone: 60%**

Tyre profile depth FL	**2.4**
Tyre profile depth FR	**3.5**
Tyre profile depth RL	**4.4**
Tyre profile depth RR	**4.4**
Tyre size FL	**205/60 R 16 96 V**
Tyre size FR	**205/60 R 16 96 V**
Tyre size RL	**205/60 R 16 96 V**
Tyre size RR	**205/60 R 16 96 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Remote ignition key, Missing, Repair/replace (lump sum)



Roof liner, Dirty, Cleaning




Inner door sill FL, Scratch(es), Paint




Floor mat F, Tear, Replace




Air vent, mid-dashboard, Broken, Replace




Interior trim, Unclasped, Dismount/Mount




Tyre FL, Out of tolerance, Replace




Tyre FR, Out of tolerance, Replace




Outside rear-view mirror housing L, Scratch(es), Replace




Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)




Side panel L, Scratch(es), Paint




Outer sill R, Dent(s) and scratch(es), Replace and paint




Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)





Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)





Bodywork, Not original part, Sticker removal small




ALPHABET

Historique Maintenance

Immatriculation: **FZ-247-RZ** Date de 1ère immatriculation: **02/06/2021**

Modèle: **Peugeot PARTNER BHDI 100 S&S 100 S&S 1000KG STD ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
09/02/2026	63.432	SOCIETE EXPLOITATION FRANCESCHINI	BATTERIE RPLT
28/01/2026	62.460	SOCIETE EXPLOITATION FRANCESCHINI	DISQUES PLAQUETTES AV RPLT
	0		REVISION
17/07/2025	52.562	SOCIETE EXPLOITATION FRANCESCHINI	FILTRE CLIM RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		FILTRE A AIR RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		ADBLUE
	0		REVISION
04/07/2025	51.866	CONTROLE TECHNIQUE AUTOMOBILE DES ESTROUBLANS	CONTROLE TECHNIQUE
25/06/2025	51.155	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
29/01/2025	42.522	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
11/09/2023	22.011	SOCIETE EXPLOITATION FRANCESCHINI	PLAQUETTES AV RPLT
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		ADBLUE
	0		REVISION
	0		LIQUIDE DE FREIN