



Skoda Octavia (UKL): 2DDG395

Vinnumber:	TMBJP8NX6PY079884	Versionname:	Octavia Combi Clever+ 1.0TSi 110pk/cv 5p
First Registrationdate:	10/02/2023	Fiscalpower:	
Expertise Mileage:	189639	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Maintenance	sinds 3200 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/17/95 V			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 17 95 V
Tyre size FR				205/55 R 17 95 V
Tyre size RL				205/55 R 17 95 V
Tyre size RR				205/55 R 17 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Spare wheel	Yes	Jack	Yes
Service, Maintenance, Check			



Windscreen, Crack, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Step L, Dent(s), Acceptable



Door FL, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Smart repair



Alloy rim RR, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Kenteken	2DDG395
Merk Model	Skoda Octavia Combi Clever+ 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	2/10/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
1/16/26	153,899	bougie	Vervangen
1/16/26	153,899	Inspectie met olie vervanging (vast in	Uitvoeren
1/16/26	153,899	klein materiaal	
1/16/26	153,899	koelwater vloeistof	Bijvullen/-laden
1/16/26	153,899	luchtfilter interieur	Vervangen
1/16/26	153,899	remschijven en blokken vooraan	Vervangen
1/16/26	153,899	ruitenswisserrubber achter	Vervangen
1/16/26	153,899	ruitenswisserrubber vooraan	Vervangen
1/16/26	153,899	ruitenswisservloeistof	Bijvullen/-laden
4/16/25	117,231	batterij	Vervangen
4/16/25	117,231	Inspectie met olie vervanging (vast in	Uitvoeren
4/16/25	117,231	klein materiaal	
4/16/25	117,231	koelwater vloeistof	Bijvullen/-laden
4/16/25	117,231	luchtfilter	Vervangen
4/16/25	117,231	remvloeistof	Vervangen
4/16/25	117,231	ruitenswisservloeistof	Bijvullen/-laden
10/9/24	89,072	batterij	Vervangen
10/9/24	89,072	bougie	Vervangen
10/9/24	89,072	Inspectie met olie vervanging (vast in	Uitvoeren
10/9/24	89,072	klein materiaal	
10/9/24	89,072	koelwater vloeistof	Bijvullen/-laden
10/9/24	89,072	luchtfilter interieur	Vervangen
10/9/24	89,072	remblokken achter	Vervangen
10/9/24	89,072	ruitenswisserrubber achter	Vervangen
10/9/24	89,072	ruitenswisserrubber vooraan	Vervangen
10/9/24	89,072	ruitenswisservloeistof	Bijvullen/-laden
5/23/24	61,693	bougie	Vervangen
5/23/24	61,693	Inspectie met olie vervanging (vast in	Uitvoeren
5/23/24	61,693	klein materiaal	
5/23/24	61,693	luchtfilter interieur	Vervangen
5/23/24	61,693	remblokken vooraan	Vervangen
10/20/23	32,726	Inspectie met olie vervanging (vast in	Uitvoeren
10/20/23	32,726	klein materiaal	
10/20/23	32,726	ruitenswisservloeistof	Bijvullen/-laden