



**RENAULT KANGOO FURGÓN L1 1.5 Blue dCi 70kW (95CV) furgón 4P manual: 6061-MCS**

Vinnnumber:	<b>VF1RFK00870152246</b>	Versionname:	
First Registrationdate:	<b>5/12/2022</b>	Fiscalpower:	<b>0</b>
Expertise Mileage:	<b>117699</b>	Power Kw:	
Bodytype:	<b>Transporter</b>	Body colour:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Steel</b>
Transmission:			
Fueltype:	<b>Diesel</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Type of rims (mounted):	<b>Steel</b>		
Certificate of Conformity:	<b>No</b>		
Category:	<b>Light Commercial Vehicle</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Radio:	
Number keys remote:	<b>2</b>	Rear parking sensors:	
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	<b>Manual climate control</b>		

**Tyres**

<b>195/65/15/95 H</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 7 mm</b>	Fr.R.	<b>Goodyear: 7 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>
Tyre profile depth FL:				<b>7.0</b>
Tyre profile depth FR:				<b>7.0</b>
Tyre profile depth RL:				<b>6.0</b>
Tyre profile depth RR:				<b>6.0</b>
Tyre size FL:				<b>195/65 R 15 95 H</b>
Tyre size FR:				<b>195/65 R 15 95 H</b>
Tyre size RL:				<b>195/65 R 15 95 H</b>
Tyre size RR:				<b>195/65 R 15 95 H</b>
Tyre type FL:				<b>Summer</b>
Tyre type FR:				<b>Summer</b>
Tyre type RL:				<b>Summer</b>
Tyre type RR:				<b>Summer</b>
Tyre make FL:				<b>259</b>
Tyre make FR:				<b>259</b>
Tyre make RL:				<b>259</b>
Tyre make RR:				<b>259</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>
-------------	------------

Registration document, Missing, Repair/replace (lump sum)



MOT certificate, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Interior, Dirty, Cleaning



Wheel bolt cover RL, Missing, Replace



Door FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Wing FR, Scratch(es), Acceptable



Rear light R, Broken, Replace



Bumper R, Scratch(es), Paint



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Rear panel, Scratch(es), Paint



Tyres, No damage, Check

