MACADAM







BMW 1 Reeks (UKL): 2CMN595

Vinnumber:	**WBA7M910605V68985**	Versionname:	**118d (F40) 2.0d 136pk/cv 5p**
First Registrationdate:	**16/09/2022**	Fiscalpower:	
Expertise Mileage:	**111578**	Power Kw:	**100**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**15000.0**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar removable**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/91 W**			
	Fr.L.	**Bridgestone: 6 mm**	Fr.R.	**Bridgestone: 4 mm**
	Re.L.	**Bridgestone: 5 mm**	Re.R.	**Bridgestone: 4 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/55 R 16 91 W**
Tyre size FR	**205/55 R 16 91 W**
Tyre size RL	**205/55 R 16 91 W**
Tyre size RR	**205/55 R 16 91 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Wing RL, Dent(s) and scratch(es), Acceptable






Bumper R, Scratch(es), Spot repair




Wing RR, Scratch(es), Repair and paint (complete)







Door RR, Scratch(es), Acceptable





Door FR, Scratch(es), Acceptable




Wing FR, Scratch(es), Acceptable




Wing FR, Scratch(es), Acceptable





Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WBA7M910605V68985

ALPHABET

Kenteken	2CMN595
Merk Model	BMW 118d (F40) 2.0d 136pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	9/16/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/24/26	101,075	batterij	Vervangen
6/24/26	101,075	BMW/MINI service standaard omvang	Uitvoeren
6/24/26	101,075	BMW/MINI service voertuig-check	Uitvoeren
6/24/26	101,075	klein materiaal	
6/24/26	101,075	ruitenwisserrubber achter	Vervangen
6/24/26	101,075	ruitenwisserrubber vooraan	Vervangen
6/24/26	101,075	ruitenwisservloeistof	Bijvullen/-laden
6/24/26	101,075	service luchtfilter	Uitvoeren
6/24/26	101,075	service microfilter	Uitvoeren
6/24/26	101,075	service motorolie	Uitvoeren
2/5/26	91,485	motorsteun	Vervangen
2/4/26	91,457	BMW/MINI service standaard omvang	Uitvoeren
2/4/26	91,457	remblokken achter	Vervangen
7/16/25	75,392	batterij	Vervangen
7/16/25	75,392	BMW/MINI service standaard omvang	Uitvoeren
7/16/25	75,392	motorkapvergrendeling	Vervangen
7/16/25	75,392	remvloeistof	Vervangen
7/16/25	75,392	ruitenwisserrubber achter	Vervangen
7/16/25	75,392	ruitenwisserrubber vooraan	Vervangen
7/16/25	75,392	service brandstoffilter	Uitvoeren
7/16/25	75,392	service microfilter	Uitvoeren
7/16/25	75,392	service motorolie	Uitvoeren
7/23/24	50,966	batterij	Vervangen
7/23/24	50,966	BMW/MINI service standaard omvang	Uitvoeren
7/23/24	50,966	BMW/MINI voertuigcontrole	Uitvoeren
7/23/24	50,966	service luchtfilter	Uitvoeren
7/23/24	50,966	service microfilter	Uitvoeren
7/23/24	50,966	service motorolie	Uitvoeren
8/28/23	26,543	batterij	Vervangen
8/28/23	26,543	BMW/MINI service standaard omvang	Uitvoeren
8/28/23	26,543	service microfilter	Uitvoeren
8/28/23	26,543	service motorolie	Uitvoeren
4/25/23	16,386	controle niveaus	Uitvoeren