

2-EWU-625

2-EWU-625 · Move! 1.0 TSI 110cv DSG bicolor · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-EWU-625	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ7RR084347
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	Move! 1.0 TSI 110cv DSG bicolor	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	22-02-2024
Color	Black	Odometer	84.168 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	81	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Landsail	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	6 ^{mm}	Landsail	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part
Fender - Rear Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Hood

Damage Type
Stonechipping

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Bumper - Front

Damage Type
small dents / small scratches

Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part
Frontdoor - Right

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Reardoor - Right

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part
Roof

Damage Type
Small dent(s)

Notes
Dakstijl

Repair Type
Restyle
Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Right	Scratch(es)	Spray	No



Damage Part

Damage Type

Repair Type

Acceptable

Interior

Stains & dirt

Cleaning

No