

2-EDE-351

2-EDE-351 · ST-line 2.5i pHEV 225pk 165kw HF45 aut · 6 August 2026 ·
Zaventem (BE)

Specifications

License Plate Number	2-EDE-351	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0FXXWPMHPS63238
Model	Kuga	Cylinder Capacity	2.488 ^{cm3}
Model Versions	ST-line 2.5i pHEV 225pk 165kw HF45 aut	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	04-09-2023
Color	Grey	Odometer	85.629 ^{Km}
Paint Type	Metallic	Numer Of Keys	1
Production Year	2023	Interior	Darkgrey - Cloth
KW	112	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Charging cable - 230v

Cruise control

Electric rear windows

Electric windows front

Leather steering wheel

Navigation system

Rear parking sensors

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Rear Left	3 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Front Right	3 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Rear Right	3 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Small scratch(es)	Panelbeating & Spotrepair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor - Right	Door-edge chipped	en deukje	Panelbeating & Spotrepair	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Front Right	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Mirror - leftside	Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Left	Small scratch(es)	Touch-up / Polish	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor - Left	Damaged	speakerkapje gebroken	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Dent(s)	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Alloys	Damaged	RV - RA - LA	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Damaged	Replace	No