MACADAM








FORD Focus: 7195-LWM

Vinnumber:	**WF0NXXGCHNNL20079**	Versionname:	**1.5 Ecoblue 70kW Trend+ berlina con portón 70kW 5P manual**
First Registrationdate:	**24/02/2022**	Fiscalpower:	
Expertise Mileage:	**127552**	Power Kw:	
Bodytype:	**Berline**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**205/60/16/92 V**			
	Fr.L.	**Goodyear: 5 mm**	Fr.R.	**Goodyear: 5 mm**
	Re.L.	**Goodyear: 3 mm**	Re.R.	**Goodyear: 3 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**205/60 R 16 92 V**
Tyre size FR	**205/60 R 16 92 V**
Tyre size RL	**205/60 R 16 92 V**
Tyre size RR	**205/60 R 16 92 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**No**

Registration document, Missing, Repair/replace (lump sum)




Bumper F, Scratch(es), Repair and paint (complete)





Wing RR, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)




Compressor, Missing, Replace




Tyres, No damage, Check






Bodywork, Glue residues, Remove lettering




ALPHABET

Datos del vehículo

Marca	FORD	Matrícula	7195-LWM
Modelo	Focus	VIN	WF0NXXGCHNNL20079
Versión	1.5 Ecoblue 70kW Trend+ berlina con portón 70kW 5P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
13/05/2024	Aleta trasera derecha | Matricula delantera	0	PLANCHA PINTURA APVC SL
30/06/2023	Pinchazo+Equilibrado	33096	REPARACIO DE L'AUTOMOBIL M.GALLEGO
04/09/2023	Revisión 2 años	40244	ROMACAR ABS S.L.
02/08/2024	Sustitución	63501	Arpa Motors, S.L.L. ARPA MOTORS, S.L.L.
27/09/2024	Escobillas Limpiaparabrisas, Líquido de Frenos, Rev. 60.000 kms	70534	SOLER AUTOMOCION S.C.P.
01/08/2025	Aceite motor - - - ALP EURO, Arandela / tapón cárter, Filtro aceite, Filtro antipolen - Nueva, Líquido lavaparabrisas, Serv inspección 90000 KM, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados	101100	ARPA MOTORS S.L.L.
09/09/2025	Fluido refrigerante a/c, Prueba larga en carretera, Puesta a disposición del vehículo, Sustituir Fluido refrigerante a/c, Sustituir Prueba larga en carretera, Verificar Anticongelante, Verificar Diagnosis	106769	ARPA MOTORS S.L.L.
24/09/2025	Desmontar y montar Desmontaje MO mecánica, Enfriador aceite motor, Puesta a disposición del vehículo, Sustituir Enfriador aceite motor	107975	ARPA MOTORS S.L.L.
03/08/2026	Batería - VARTA - Rec.Plat. EuroTaller - 60AH - Nueva, Importe de pago por uso, Líquido lavaparabrisas, Puesta a disposición del vehículo, Sustituir Batería, Sustituir Líquido lavaparabrisas, Verificar Batería	122120	ARPA MOTORS S.L.L.
23/04/2025	Desmontar y montar Desmontaje MO mecánica, Prueba larga en carretera, Sustituir Prueba larga en carretera, Verificar Diagnosis	901050	ARPA MOTORS S.L.L.

Fecha	Descripción	Kilómetros	Taller