

INSPECTION REPORT

End of contract

GENERAL INFO

File	316359
License plate	2CEZ060
Vehicle identification number	W1K2062541F064605
Dossier	2022 091 060
Make	Mercedes C Break 300e 230kW Lu
Mileage	98891
First registration	29/06/2022
client availability date	26/06/2026
inspectionDate	01/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
227	Side View Mirror Right / Shell / Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
150	Rear Bonnet // Smart Repair Small	Y
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
346	Tyre Front Right // Replace	N
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y
883	Key Price Range 2 //	Y

Damage Pictures



Wing Front right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Polish-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Front Right Door Interior Coating // Replace Completely-scratch




Rocker Panel Left // Smart Repair Medium-dent



Roof // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-dent




Rear Bonnet // Smart Repair Small-dent




Wing Rear Right // Repair & Painting-scratch + dent




Tyre Front Right // Replace-worn



Interior // Repair 1-worn



Key Price Range 2 //-worn



Light / Rear Right / Replace-scratch



Light / Rear left / Replace-scratch




Wheel Two Tone Rear Right // Repair-scratch




Bumper Rear // Painting-scratch



Door Front Right // Polish-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch