



SEAT Ibiza: 6033-MML

Vinnnumber:	VSSZZKJ7RR019207	Versionname:	1.0 MPI 59kW (80CV) Reference XM berlina con portón 59kW 5P manual
First Registrationdate:	28/12/2023	Fiscalpower:	
Expertise Mileage:	37453	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Petrol		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	No		
Category:	VS		
Registration Certificate Car (BE):	No		

Options


Number of keys total	1
Number keys remote	1
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of climate control	Manual climate control

Tyres

185/65/15/88 H				
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 4 mm	Re.R.	Hankook: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Repair kit	No
MOT certificate, Missing, Repair/replace (lump sum)	



Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Seat cover FR, Tear, Replace



Interior, Dirty, Cleaning



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Tyre repair kit, Missing, Repair/replace (lump sum)



Tyres, No damage, Check



