



RENAULT ESPACE

Vinnumber:	VF1RFC00565957614	Versionname:	Blue dCi 160 EDC Corporate Edition
First Registrationdate:	20/11/2020	Fiscalpower:	
Expertise Mileage:	177288	Power Kw:	118
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2315
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining artificial leather	Type of Tow bar	Tow bar collapsible
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

235/60/18/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/60 R 18 92 H
Tyre size FR				235/60 R 18 92 H
Tyre size RL				235/60 R 18 92 H
Tyre size RR				235/60 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1000,60
Bonnet, Chemical pollution, Polish	0,00



Bumper moulding F, Scratch(es), Acceptable 0,00



Door RL, Bad repair, Check 0,00



Wing RL, Chemical polution, Repair and paint (complete) 517,89



Step L, Scratch(es), Acceptable 0,00




Door FL, Bad repair, Check 0,00



Wing FL, Scratch(es), Acceptable 0,00




Bumper R, Scratch(es), Acceptable 0,00



Bumper trim R, Scratch(es), Smart repair 116,69



Rear window, Scratch(es), Polish 0,00



Bumper moulding R, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Door RR, Scratch(es), Acceptable 0,00



Step R, Dent(s) and scratch(es), Repair and paint (complete) 161,81



Wing RR, Dent(s), Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00

