

2-DJH-043

2-DJH-043 · Move! 1.0 TSI 95cv 5v unicolor · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DJH-043	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJXPR102689
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	Move! 1.0 TSI 95cv 5v unicolor	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	28-03-2023
Color	Blue	Odometer	91.046 ^{km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Grey
KW	70	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Delinte	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	5 ^{mm}	Delinte	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Reardoor - Left

Damage Type

small dents / small scratches

Repair Type

Restyle / Touch-up

Acceptable

No



Damage Part

Frontdoor - Left

Damage Type

Damaged

Repair Type

Touch-up / Polish

Acceptable

No



Damage Part

Hood

Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Frontdoor - Right

Damage Type

Small scratch(es)

Repair Type

Polish

Acceptable

No



Damage Part

Fender - Rear Right

Damage Type

small dents / small scratches

Repair Type

Restyle / Touch-up

Acceptable

No



Damage Part

Bumper - Rear

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Interior

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Trunkshelf

Damage Type

Missing

Repair Type

Replace

Acceptable

No