

DEKRA Automotive Solutions

Vehicle details

VIN	WDD247003 1J022598	Registration date	01/01/1900	Exterior Color	Unknown
Brand	MERCEDES	Licence Plate	2CEP318	Odometer	130 620 km
Model	CLASSE B				

Inspection Details

Arrival Date	03/06/2026	Inspection ID	7031219	Inspection date	30/06/2026
Assign Date	03/06/2026	Fleet owner	LIZY Belgique	Inspection loc.	Parc Lizy



Generic equipment



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Rear parcel shelf	✓

Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓
Spare key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres





Hankook 205/60/16 V All seasons 5.0 mm

Hankook 205/60/16 V All seasons 5.0 mm

Hankook 205/60/16 V All seasons 5.0 mm

Hankook 205/60/16 V All seasons 5.0 mm

Damages

1		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	90.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	90.00€	<b>Net Cost</b>	<b>90.00€</b>
		-					
2		Part	Tailgate / Boot door	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Gross Cost	147.00€
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	147.00€	<b>Net Cost</b>	<b>147.00€</b>
		x3					

DEKRA Automotive Solutions

3		Part	Door sill	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
4		Part	Door	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	-
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
5		Part	Door	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-

Summary Inspection

Gross Price	237.00€	Depreciation	-	Net Price	237.00€
-------------	---------	--------------	---	-----------	---------

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	0.00€	0.00	0.00€	-	-	0.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	0.00€	-	-	0.00€
Flat Rate	237.00€	-	-	237.00€

Signatures

<b>Signature Receiver</b>	<b>Signature Expert</b>	<b>Signature Customer / Driver</b>
		 <p>Xelis</p> <p>30-08-26 08:22</p>