APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	
Make:	BMW
Model / version:	IX3
Vin:	WBY7X41070S105640
Plate:	
Mileage:	104739
First registration:	14/09/2021
Color:	Sophistograu

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES



































VIN INFORMATION

2021	Mai	Matière : alliage
Lettre repère (J)	Diamètre avant 19	Diamètre arrière 19
Largeur avant 8,0	Largeur arrière 8,0	Diamètre avant 19
Diamètre arrière 19	Hauteur avant 50	Hauteur arrière 50
Indice de vitesse avant W	Indice de vitesse arrière W	Largeur avant 245

Largeur arrière 245
210 kw
Rétroviseur gauche jour/nuit automatique
Rétroviseur intérieur jour/nuit automatique
Garnitures simili-cuir
Alarme
Fixotoit aluminium satiné
Avertisseur d'angle mort
éclairage d'ambiance
protection acoustique des piétons
chargeur sans fil

spécifique Europe

Climatisation réfrigérant 1234YF
285 ch
Rétroviseur droit jour/nuit automatique
Siège avant gauche chauffant

Caméra avant
Appel de secours
Protection piéton
Contrôle pression des pneus
tuner DAB
BMW Live Cockpit Pro
encarts intérieurs noir brillant avec accents perle brillant chromés

Electrique
Minérale vernissée
Rétroviseurs rabattables électriques
Sièges avant chauffants

Régulateur automatique de la distance
Attelage avec boule rétractable électrique
Assistant maintien de la voie
Executive
filet de séparation coffre
Parkassistent
encarts décoratifs Frozen Grey

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer	Aluminium	?
Front right	5 mm			Summer	Aluminium	?
Rear left	5 mm			Summer	Aluminium	?
Rear right	5 mm			Summer	Aluminium	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Door RL	Scratch(es)

Total: 1

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

2 - Door RL - Scratch(es)





1 - Bodywork - Dent(s) and scratch(es) - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

06/10/2026 10:09