



FORD Kuga: 3382-MFW

Vinnumber:	WF0FXXWPMHNG15615	Versionname:	ST-Line X 2.5 Duratec FHEV 140kW 4x4 Aut todoterreno 140kW 5P automática
First Registrationdate:	29/03/2023	Fiscalpower:	
Expertise Mileage:	241985	Power Kw:	
Bodytype:	SUV	Body colour	White
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Seats electric F L
Number keys remote	2	Central consol F
GPS big screen color		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		Roof bar black
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	245/45/20/103 W			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/45 R 20 103 W
Tyre size FR				245/45 R 20 103 W
Tyre size RL				245/45 R 20 103 W
Tyre size RR				245/45 R 20 103 W
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Boot lid covering R, Scratch(es), Replace



Interior, Dirty, Cleaning



User's manual, Missing, Repair/replace (lump sum)



Service book, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Wing RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing FR, Scratch(es), Repair and paint (complete)



Wing trim FR, Scratch(es), Paint



Tyre FR, Tear, Acceptable



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Outer door handle RR, Scratch(es), Paint



Wing RR, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Acceptable



Datos del vehículo

Marca	Matrícula
Modelo	VIN
Versión	

Histórico

Fecha	Descripción	Kilómetros	Taller

Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller