



Expertise

Protocol number: 46412004
Order No. / Reference: 26520550
Inspection date: 8 Jul 2026

Manufacturer: Volkswagen

Model: Tiguan 2.0 TDI SCR DSG Elegance

VIN: WVGZZZ5NXPW525382



Vehicle details

Manufacturer / Type / Model / Equipment

Volkswagen Tiguan 2.0 TDI SCR DSG Elegance

Vehicle Identification number	WVGZZZ5NXPW525382
Mileage (Read)	178,374 km
First registration	3 May 2023
Number of holders	1
Next periodical technical inspection	05/2028
(Report on hand)	

Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV

Colour / colour code	Delfingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Dark grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	29,300 km
Last service on / at	05/2026 at 177,658 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS483651
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / BZG 25430		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,200 kg	Empty weight	
Dimensions	4509 x 1839 x 1651		

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/45 R20 100W	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	235/45 R20 100W	Summer tyres on Light alloy	Pirelli	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tyres on Steel rim with wheel cover	Continental	5mm / 5mm
2)	215/65 R17 99H	Winter tyres on Steel rim with wheel cover	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	145/85 R18 103M	All-season tyres on Steel	Sonstige	4 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Turning and bad weather lights
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Adaptive Cruise Control (ACC) (DSG)
- Electrically adjustable and heated exterior mirrors
- Chrome applications on mirror adjustment switches, window regulator switches, door pull handles
- Display: Digital Cockpit Pro, multicolor, various selectable info profiles
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Windscreen made of laminated safety glass, heat and sound insulating
- Tailgate with electric opening and closing, adjustable opening angle
- Interior mirror automatically dimming
- LED license plate lighting
- Combination instrument cluster with electronic speedometer
- LED reading lights, 2 in the front and 2 in the rear
- Steering wheel: Multifunction leather steering wheel, heated, with paddle shifters
- Dynamic headlight range control
- Fatigue detection
- Non-smoking version
- Package: Ambiance Package
- Package: Winter
- Radio
- Rain sensor
- Wheels: AirStop tires 235/55 R 18, rolling resistance class A
- Drawers under the front seats
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Lumbar support in the front
- Seats: Top comfort seats in the front
- Lane keeping assistant "Lane Assist"
- 12-volt socket
- Bumpers in body color
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear
- Airbag for driver and front passenger including knee airbag on the driver's side
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- third brake light
- Silver anodized roof rails
- Diesel particulate filter
- Tachometer
- Parking assistance
- Electronic Stability Program with counter-steering support
- Electric windows front and rear
- High beam control Light Assist
- Pedestrian detection
- Transmission: 7-speed DSG
- Rear window heated
- rear window wiper
- ISOFIX mounting points, also for i-Size child car seats
- Air conditioning system "Air Care Climatronic"
- Rear headrests (3)
- Front headrests
- LED matrix headlights with LED daytime running lights and cornering lights
- Light in the front footwell
- Front center armrest adjustable in height and length, with storage box and rear air vents
- Emergency call service
- Package: Chrome package
- Padding: Microfleece
- Radio accessories: 8 speakers
- Tire pressure monitoring system
- Wheels: Tire Mobility Set omitted
- Gearshift knob in leather
- electromechanical power steering
- Seats: Front passenger seat backrest folds down completely
- Seats: Rear bench seat asymmetrically split
- Seats: Front seats with height adjustment
- Start-stop system with brake energy recuperation
- Power outlet: 2 USB-C ports on the front
- Textile floor mats front and rear
- Prepared for later activation: Navigation function "Discover Media" incl. "Streaming & Internet"
- Central locking without safe locking, with remote control and 2 remote keys



Extra equipment

- Electrically adjustable, folding, and heated exterior mirrors, ambient lighting, passenger-side mirror lowering function
- Driving profile selection
- Paint finish: Metallic
- LED matrix headlights - IQ.LIGHT (Dynamic Light Assist high beam control for LED matrix headlights - LED headlights with LED daytime running lights and cornering lights - LED taillights, dark red)
- Mesh partition
- Package: "Easy Open & Close" with safe locking mechanism ("Easy Open & Close" - tailgate with sensor-controlled opening and closing, with remote unlocking - keyless locking and starting system "Keyless Access" with safe locking mechanism)
- Package: Business Premium (DSG) (App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Leather multifunction steering wheel, heated, with shift paddles - Automatically heated front windscreen washer nozzles - Voice control - "Comfort" telephone interface with inductive charging function - Heated front seats)
- Package: Cargo package including space- and weight-saving spare wheel (230V socket in the luggage compartment - on-board tools and jack - luggage compartment lighting - luggage compartment floor height-adjustable in 2 stages - space- and weight-saving spare wheel)
- Rear View reversing camera
- Seats: ergoActive front seats (ergoActive front seats height-adjustable, seat and backrest tilt adjustable, thigh support longitudinally adjustable - lumbar support front electrically adjustable and with massage function)
- Anti-theft alarm system with safe locking (anti-theft alarm system with interior monitoring, backup horn and tow-away protection, central locking with safe locking, remote control and 2 remote folding keys)
- Navigation system "Discover Media" incl. "Streaming & Internet" (20.3 cm TFT touchscreen - FM radio reception - Dual tuner with phase diversity for best possible radio reception - Radio Data System (RDS) - Radio station logos - MP3 playback - USB-C interface with Apple compatibility - 4 x 20 watt output power - Map with 2D display - 3-band sound control - Telephone interface - Traffic sign recognition - Points of interest - DAB+ digital radio reception)
- Package: "IQ.DRIVE" assistance package including "Emergency Assist" (Driving assistant "Travel Assist", Lane Assist lane keeping assistant and "Emergency Assist" - Parking assistant "Park Assist" including parking aid - Proactive occupant protection system in conjunction with "Front Assist" - Lane change assistant "Side Assist" and parking assist - Traffic sign recognition)
- Package: Sport package (progressive steering - tinted rear side windows and rear window - sport suspension)
- Park Assist system including parking aid
- Tire pressure monitoring system
- Wheels: Alloy (4) "Cape Town" 8 J x 20 Volkswagen R (4 alloy wheels 8 J x 20 in grey metallic - AirStop tires 235/45 R 20 - wheel locks with extended theft protection)
- Auxiliary heating and ventilation (with radio remote control and timer)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratch(es) - Smart repair
2	Vehicle glazing	Rear window - Glued / labelled - Remove
3	Door - front right side	Door - dent(s) - Smooth repair work
4	Side panel - rear left side	Sill - dent(s) - Smooth repair work
5	Door - front left side	Door edge - Scratch(es) - Smart repair
6	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
7	Wheel / tyres	Alloy rim - rear left side - Scratched - Loss in value
8	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
9	Front bumper	Spoiler - Scratched - Loss in value
10	Wing mirror - right side	Mirror housing - Scratch(es) - Paint
11	Mudguard - right side	Wheel well extension - Scratched - Replace
12	Rear bumper	Rear bumper - Scratch(es) - Paint
13	Bonnet	Bonnet - Stone chips - Paint
14	Front bumper	Front bumper - Scratched - Paint
15	Vehicle glazing	Rear window - Scratch(es) - Replace
16	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
17	Wheel / tyres	Alloy rim - front left side - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Door - front right side	Door edge - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Log book

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der Winterradsatz ist kein Bestandteil der Ausstattungsliste.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Vehicle glazing: Rear window - Glued / labelled - Remove



Damage 2: Vehicle glazing: Rear window - Glued / labelled - Remove




Damage 2: Vehicle glazing: Rear window - Glued / labelled - Remove



Damage 3: Door - front right side: Door - dent(s) - Smooth repair work



Damage 3: Door - front right side: Door - dent(s) - Smooth repair work



Damage 4: Side panel - rear left side: Sill - dent(s) - Smooth repair work



Damage 4: Side panel - rear left side: Sill - dent(s) - Smooth repair work



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 7: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 7: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 7: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 9: Front bumper: Spoiler - Scratched - Loss in value



Damage 9: Front bumper: Spoiler - Scratched - Loss in value



Damage 10: Wing mirror - right side: Mirror housing - Scratch(es) - Paint



Damage 10: Wing mirror - right side: Mirror housing - Scratch(es) - Paint




Damage 11: Mudguard - right side: Wheel well extension - Scratched - Replace



Damage 11: Mudguard - right side: Wheel well extension - Scratched - Replace




Damage 11: Mudguard - right side: Wheel well extension - Scratched - Replace



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Bonnet: Bonnet - Stone chips - Paint




Damage 13: Bonnet: Bonnet - Stone chips - Paint




Damage 13: Bonnet: Bonnet - Stone chips - Paint




Damage 13: Bonnet: Bonnet - Stone chips - Paint




Damage 14: Front bumper: Front bumper - Scratched - Paint




Damage 14: Front bumper: Front bumper - Scratched - Paint



Damage 14: Front bumper: Front bumper - Scratched - Paint



Damage 14: Front bumper: Front bumper - Scratched - Paint



Damage 15: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 15: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 15: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 16: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 16: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 17: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 17: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 17: Wheel / tyres: Alloy rim - front left side - Scratched - Replace

Damage 17: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZ5NXPW525382

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Tiguan 2.0 TDI SCR DSG
Elegance

Datum	KM-Stand	Beschreibung
20.05.2026	177.658	AU; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
08.10.2025	146.857	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben hinten; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
13.05.2025	117.274	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Getriebeöl ern/ prüfen; Keilrippenriemen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.10.2024	87.471	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
15.05.2024	60.002	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
07.11.2023	33.824	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges