

Audi

2.0 30 TDI 85KW S LINE

VIN: WAUZZZGY2MA104807



Description

|                        |                   |                         |
|------------------------|-------------------|-------------------------|
|                        | Registration date | Odometer                |
|                        | 03/05/2021        | 114082 km               |
| Color                  | Year              | Upholstery              |
| Bleu Navarre Métallisé | 2021              | -                       |
| Number of doors        | Number of seats   | Generation              |
| 5                      | 5                 | -                       |
| Engine displacement    | Gearbox type      | Engine type             |
| 1968                   | Manual            | Combustion              |
| Fuel Type              | Number of gears   | Drivetrain              |
| Diesel                 | 6                 | Front Wheel Drive (FWD) |
| Max power              |                   |                         |
| 85 KW                  |                   |                         |

Vehicle Equipments

|                      |                  |                     |
|----------------------|------------------|---------------------|
| Automatic headlights | Cruise control   | Climate control     |
| Park Assist          | Alloy wheel rims | Front sensors       |
| Rear sensors         | SATNAV           | Heated door mirrors |
| Xenon headlights     |                  |                     |

Control

Detected issues

|                   |      |                        |      |
|-------------------|------|------------------------|------|
| Engine / Sound    | ✓ Ok | Vehicle leak proofness | ✓ Ok |
| Exhaust / Clarity | ✓ Ok |                        |      |

Defects & corrections

| #   | Element                         | Defect    | Correction |
|-----|---------------------------------|-----------|------------|
| 001 | Floor mat / Interior Front Left | Burn mark | Acceptable |



002

Rim / Front Left

Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Painted

Scratched

Repair



003

Rim / Front Right

Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Painted

Scratched

Repair



004

Bumper / Front

Painted : Yes

Scratched

Acceptable



005

Rim / Back Left

Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Painted

Scratched

Repair



006

Door sill / Interior Back Left

Dent

Acceptable




007

Wing / Back Left

Improper Repair

Repair



008 Bumper / Back <sup>1</sup>  
Painted : Yes

Scratched


Smart repair



009 Tailgate / Boot door / Back <sup>2</sup>

Dent

Smart repair



010 Rear windscreen / -  
Tinted window : No

Sticker

Removal



011 Interior tailgate lining / Back

Scratched

Acceptable



012 Tailgate spoiler / Back  
Painted : Yes

Paint etching


Painting



013 Rim / Back Right  
Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Painted

Scratched

Repair

|                                                                                                                                                                                                                                                                                                                                                    |                                                      |               |              |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|---------------|--------------|
| <div></div>                                                                                    |                                                      |               |              |
| 014                                                                                                                                                                                                                                                                                                                                                | Door / Front Right                                   | Dent          | Acceptable   |
| <div></div>                                                                                                                                                                                                                                                       |                                                      |               |              |
| 015                                                                                                                                                                                                                                                                                                                                                | Roof / Exterior Exterior                             | Paint etching | Painting     |
| <div></div> |                                                      |               |              |
| 016                                                                                                                                                                                                                                                                                                                                                | Door / Back Right                                    | Dent          | Acceptable   |
| <div></div>                                                                                                                                                                                                                                                     |                                                      |               |              |
| 017                                                                                                                                                                                                                                                                                                                                                | Carpet / Interior Front Left                         | Burn mark     | Smart repair |
| <div></div>                                                                                                                                                                  |                                                      |               |              |
| 018                                                                                                                                                                                                                                                                                                                                                | Seat / Interior Front Left<br>Trim material : Fabric | Burn mark     | Smart repair |
| <div></div>                                                                                                                                                                  |                                                      |               |              |

<sup>1</sup> x2

<sup>2</sup> x2



Loose Items

- ☐ Rear parcel shelf
- ☐ Tyre repair kit complete
- ☐ Document holder
- ☐ Registration certificate owner
- ☐ Toolkit
- ☐ Jack handle crank
- ☐ Slow charging cable (Type 2, Mode 2)
- ☐ Charging cable bag
- ☐ Spare Key
- ☐ Service book
- ☐ Towing hook
- ☐ Cargo net
- ☐ Remote key
- ☐ Security Kit
- ☐ Triangle
- ☐ Warranty booklet
- ☐ Hook /Hicth ball
- ☐ Card key
- ☐ Locking wheel nuts key
- ☐ Conformity certificate
- ☐ Spare wheel tyre
- ☐ Quick charging cable (Type 2, Mode 3)
- ☐ Safety vest
- ☐ Remote control
- ☐ Compressor tyre repair kit
- ☐ First aid kit
- ☐ User manual
- ☐ Jack
- ☐ Load cover
- ☐ Refill tyre repair kit
- ☐ Registration certificate
- ☐ Satellite navigation
- ☐ In-car tools
- ☐ Locking wheel nut

Main set of tyres

|             |             |                        |      |
|-------------|-------------|------------------------|------|
| Front Left  | HANKOOK     | 225 / 45 / 17 / Winter | 7 mm |
| Front Right | HANKOOK     | 225 / 45 / 17 / Winter | 7 mm |
| Back Left   | CONTINENTAL | 225 / 45 / 17 / Winter | 7 mm |
| Back Right  | CONTINENTAL | 225 / 45 / 17 / Winter | 7 mm |

Comments

## Pictures



Front left



Rear left



Boot opened




Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation




Spare Tyre




Vin







Other




Other



Other



Other



Other



Floor mat / Interior Front Left / Bum mark



Floor mat / Interior Front Left / Bum mark




Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched





Rim / Back Left / Scratched



Rim / Back Left / Scratched



Rim / Back Left / Scratched



Door sill / Interior Back Left / Dent



Wing / Back Left / Improper Repair



Wing / Back Left / Improper Repair



Wing / Back Left / Improper Repair



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched




Bumper / Back / Scratched



Tailgate / Boot door / Back / Dent



Tailgate / Boot door / Back / Dent



Tailgate / Boot door / Back / Dent




Rear windscreen / - / Sticker





Rear windscreen / - / Sticker



Interior tailgate lining / Back / Scratched



Tailgate spoiler / Back / Paint etching



Tailgate spoiler / Back / Paint etching



Tailgate spoiler / Back / Paint etching



Rim / Back Right / Scratched



Rim / Back Right / Scratched




Rim / Back Right / Scratched



Door / Front Right / Dent



Roof / Exterior Exterior / Paint etching



Roof / Exterior Exterior / Paint etching



Roof / Exterior Exterior / Paint etching



Roof / Exterior Exterior / Paint etching



Door / Back Right / Dent



Carpet / Interior Front Left / Bum mark



Carpet / Interior Front Left / Burn mark



Seat / Interior Front Left / Burn mark



Seat / Interior Front Left / Burn mark