



2-FAJ-882 · Move! 1.0 TSI 110cv DSG unicolor · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FAJ-882	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ0RR087011
Model	Arona	Cylinder Capacity	999 ^{cm3}
Model Versions	Move! 1.0 TSI 110cv DSG unicolor	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	06-03-2024
Body Type	5 door hatchback	Odometer	88.049 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	81		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Delinte	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	2 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	4 ^{mm}	Delinte	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	2 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Fender – Rear Right

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Reardoor – Right

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Interior

Damage Type

Damaged

Notes

Vloerbedekking

Repair Type

Cloth Repair

Acceptable

No



Damage Part

Interior

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

spoiler RB

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes