



## PEUGEOT 3008

Immatriculation	-
VIN	VF3MRHNSMMS095370
Kilométrage	105 539 km
Première immatriculation	30/03/2021
Couleur carrosserie	Noir

### DÉTAILS DE L'INSPECTION

Adresse d'inspection \_\_\_\_\_ Date de l'inspection **08/06/2026 13:09:14**

Adresse d'inspection \_\_\_\_\_

### INFORMATIONS SUR LE VÉHICULE

Marque	PEUGEOT	Type de carrosserie	SUV
Modèle	3008	Nbre portes	5
VIN	VF3MRHNSMMS095370	Nbre sièges	5
Première immatriculation	30/03/2021	Transmission	Avant
Kilométrage	105 539 km	Couleur intérieur	Noir
Catégorie	Vehicule particulier	Couleur carrosserie	Noir

### DOCUMENTS ET CLÉS

Carnet d'entretien	Oui	Manuel d'utilisation	Oui
Nbre clés total	1	Certificat immatriculation (original)	Non
Nbre clés télécommandes	1	Certificat immatriculation (original)	N/A

### OPTIONS

Batterie fonctionnante	Oui	Camera de recul	Oui
Moteur fonctionnant	Oui	Cache bagages	Oui
Véhicule roulant	Oui	Compresseur	Oui
Niveau carburant	25	Kit réparation	Oui
GPS	Oui	Nature de peinture	Metallisé

### PNEUS

#### Pneus montés

Emplacement	Position	Profondeur des sculptures	Fabricant	Dimensions	Type de pneu	Type de jantes	Runflat
Avant	Gauche	4,3 mm	Michelin	225/55 R 18 102 V	Eté	Aluminium	Non
Avant	Droite	4,1 mm	Michelin	225/55 R 18 102 V	Eté	Aluminium	Non
Arrière	Gauche	6,1 mm	Michelin	225/55 R 18 102 V	4 Saisons	Aluminium	Non
Arrière	Droite	5,9 mm	Michelin	225/55 R 18 102 V	4 Saisons	Aluminium	Non



## DAMAGES



### Wing RR

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)



### Door RL

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)



### Door FR

Damage type

Scratch(es)

Repair mode

Paint



### Tailgate / Boot

Damage type	Stone chip(s)
Repair mode	Paint



### Seat cover FL

Damage type	Tear
Repair mode	Smart repair LEATHER



**Backrest cover FL**

Damage type	Tear
Repair mode	Smart repair LEATHER



**Remote ignition key (no insert)**

Damage type	Missing
Repair mode	Repair/replace (lump sum)



**Boot moulding**

Damage type	Scratch(es)
Repair mode	Replace



**Wing trim RR**

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



**Seat cover R**

Damage type	Stain
Repair mode	Cleaning



**Parking sensor F**

Damage type	Missing
Repair mode	Replace



**Dashboard**

Damage type	Scratch(es)
Repair mode	Acceptable



**Gear shift lever knob**

Damage type	Worn
Repair mode	Acceptable



**Outer door handle FL**

Damage type	Scratch(es)
Repair mode	Polish



**Wing RL**

Damage type	Scratch(es)
Repair mode	Polish



**Bonnet**

Damage type	Scratch(es)
Repair mode	Polish



**Bumper F**

Damage type	Scratch(es)
Repair mode	Polish



**Bumper spoiler F**

Damage type	Scratch(es)
Repair mode	Acceptable



**Door RR**

Damage type

Scratch(es)

Repair mode

Polish



**Wing trim FR**

Damage type

Scratch(es)

Repair mode

Acceptable



**Outside rear-view mirror housing R**

Damage type

Scratch(es)

Repair mode

Polish



**Rear floor trunk**

Damage type	Scratch(es)
Repair mode	Acceptable



**Wheel arch RR**

Damage type	Scratch(es)
Repair mode	Polish

## COMMERCIAL PHOTOS

