

2-FLP-534

2-FLP-534 · ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper - leather seats · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FLP-534	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPRG10596
Model	Focus	Cylinder Capacity	999 ^{cm³}
Model Versions	ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 - Clipper - leather seats	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	11-06-2024
Color	Silver	Odometer	72.443 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Black
KW	114	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Goodride	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	5 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	4 ^{mm}	Goodride	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	5 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	None					

Damages



Damage Part
Frontdoor - Left

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No




Damage Part
Alloy - Left Front

Damage Type
Damaged

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Foglight - Right

Damage Type
Stonechipping

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Bumper - Front

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Alloy - Right Front

Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
Fender - Front Right

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Right Rear	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Rear door - Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Small dent(s)

Restyle

No



Damage Part

Damage Type

Repair Type

Acceptable

Roof

Small dent(s)

Restyle

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Roof

Small dent(s)

Dakstijl

Restyle

No