



DACIA Duster: 5849-MCK

Vinnumber:	VF1HJD40070070236	Versionname:	Comfort Blue dCi 85kW (115CV) 4X4 todoterreno
First Registrationdate:	24/11/2022	Fiscalpower:	85kW 5P manual
Expertise Mileage:	298040	Power Kw:	
Bodytype:	SUV	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		Roof bar black
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Manual climate control	

Tyres

215/65/16/102 H				
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/65 R 16 102 H
Tyre size FR				215/65 R 16 102 H
Tyre size RL				215/65 R 16 107 T
Tyre size RR				215/65 R 16 107 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Interior covering A pillar R, Scratch(es), Repair/replace (lump sum)



Boot lid covering R, Scratch(es), Repair/replace (lump sum)



Seat cover FL, Hole, Repair/replace (lump sum)



Steering wheel, Worn, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Wing FL, Scratch(es), Repair and paint (complete)




Outside rear-view mirror L, complete, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding F, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Acceptable



Boot cover, Broken, Repair/replace (lump sum)



Bumper moulding R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering



