



VOLKSWAGEN TOURAN: [REDACTED]				
Vinnumber:	WVGZZZ1TZLW040829	Versionname:	1.5 TSi Trendline	
First Registrationdate:	3/06/2020	Fiscalpower:		
Expertise Mileage:	125623	Power Kw:	110	
Bodytype:		Body colour	Blue	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel	
Transmission:		Parking lot	2528	
Fueltype:	Petrol			
Maintenance	OK			
Type of rims (mounted)	Steel			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Sun Roof electric		
Cruise Control		Panoramic roof		
Steering wheel multifunctional		Luggage cover		
Radio multimedia		Front parking sensors		
Type of headlighting	Headlighting Halogen	Rear parking sensors		
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar	
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Type of GPS storage	SD present			
Limited Technical Inspection				
Tyres				
Summer tyres:	205/55/16/96 W			
	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Pirelli: 2 mm	Re.R.	Pirelli: 2 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				205/55 R 16 96 W
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/55 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				264
Tyre make RR				264
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				1921,42
Bonnet, Dent(s), Acceptable				0,00



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)

326,34



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)

397,58



Wheel cover FL, Scratch(es), Replace

62,38



Door FL, Scratch(es), Acceptable

0,00




Door RL, Dent(s) and scratch(es), Repair and paint (complete)

475,54



Wheel cover RL, Scratch(es), Replace

62,38



Tyre repair kit, Broken, Replace

0,00



Boot lid covering R, Repaired, Acceptable	0,00
---	------



Boot carpet, Dirty, Chemical cleaning	50,00
---------------------------------------	-------




Tailgate / Boot, Scratch(es), Repair and paint (complete)	422,44
---	--------



Wheel aperture RR, Dent(s)	0,00
----------------------------	------



Wheel aperture RL, Scratch(es), Acceptable	0,00
--	------



Wheel cover RR, Scratch(es), Replace	62,38
--------------------------------------	-------



Wing RR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Wheel cover FR, Scratch(es), Replace	62,38
--------------------------------------	-------



Wing FR, Scratch(es), Acceptable	0,00
----------------------------------	------

