MACADAM










CITROÃ‹N BERLINGO: FW-594-AF

Vinnumber:	**VR7EFYHYCLN541184**	Versionname:	**CITROÃ‹N BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**21/12/2020**	Fiscalpower:	
Expertise Mileage:	**39019**	Power Kw:	**75**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Dark Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**3**	Radio	
Number keys remote	**1**	Front parking sensors	
GPS big screen color		Rear parking sensors	
GPS storage		Sliding door right-side	
GPS storage	**HD**	Rear view camera	
Windows electric F		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/65/15/91 H**			
	Fr.L.	**Michelin: 40%**	Fr.R.	**Michelin: 40%**
	Re.L.	**Michelin: 45%**	Re.R.	**Michelin: 45%**

Tyre profile depth FL	**5.6**
Tyre profile depth FR	**5.5**
Tyre profile depth RL	**5.4**
Tyre profile depth RR	**5.3**
Tyre size FL	**195/65 R 15 91 H**
Tyre size FR	**195/65 R 15 91 H**
Tyre size RL	**195/65 R 15 91 H**
Tyre size RR	**195/65 R 15 91 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Seat cover FR, Stain, Cleaning




Seat cover FL, Stain, Cleaning




Door panel FR, Broken, Replace




Tyre FL, Tear, Replace




Side wall RL, Dent(s), Repair and paint (complete)








Bumper F, Broken, Replace




Bumper F, Scratch(es), Paint






Side wall RR, Dent(s), Repair and paint (complete)






Boot door panel RL, Dent(s), Repair and paint (complete)






Bumper corner RR, Broken, Replace




Bumper R, Deformed / Strained, Repair and paint (complete)




Boot door panel RR, Dent(s), Repair and paint (complete)




ALPHABET

Historique Maintenance

Immatriculation: **FW-594-AF** Date de 1ère immatriculation: **21/12/2020**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
12/02/2026	33.303	NOISY AUTO CONCEPT	ADBLUE
	0		CONTROLE TECHNIQUE
	0		PLAQUE IMMATRICULATION AV RPLT
	0		LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET CARBURANT
17/11/2023	19.280	NOISY AUTO CONCEPT	FEU ARD RPLT
28/04/2023	16.749	EUROMASTER FRANCE	PERMUTATIONS PNEUS
	0		REMPLACEMENT PNEUS ETE
30/01/2023	15.539	NOISY AUTO CONCEPT	ADBLUE
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM
	0		LAMPE AR RPLT
09/01/2023	15.250	FRANCE PARE BRISE SAS	CUSTODE ARG RPLT