

# MACDAM

## Mercedes-Benz EQA '21 BEV

### Vehicle information



Make:	<b>Mercedes-Benz</b>	License:	
Gearbox:	<b>Automatic</b>	Body color:	
Model:	<b>EQA '21 BEV</b>	VIN:	<b>W1N2437011J020154</b>
Fuel type:	<b>Electric</b>	Power:	<b>140 kW</b>
Version:	<b>EQA 250 Bus. Sol. AMG</b>	First registration	<b>15/10/2021</b>
Mileage:	<b>196463 km</b>	N° of doors:	

### Damage summary

Front	5
Interior	1
Rear	1
Right	1

### Commercial pictures





**Batterijcertificaat**  
 Datum van diagnose: 02/07/2026

96.51%  
 Status van de gezondheid (SOH)\*

**Mercedes EQA 250**  
 VIN : W1N243701J020154  
 Kilometerstand : 196.463 km

\*SOH berekend op basis van fabriekgegevens, informatie om rekening mee te houden voor de fabrikagewijze

Meer weten over: [www.get-moba.com](http://www.get-moba.com)

CARA



### Options according to the inspector

Central consol F	<b>Yes</b>	GPS	<b>Yes</b>	Headlights Xenon/LED/Laser	<b>Yes</b>
Hook	<b>Yes</b>	Panoramic roof	<b>Yes</b>	Radio multimedia	<b>Yes</b>
Rear view camera	<b>Yes</b>	Sun Roof electric	<b>Yes</b>	Telephone equipment	<b>Yes</b>



### Damages

#### Bonnet

Stone chip(s)

Repair and paint (complete)

Front




**Bumper F**

Scratch(es)

Repair and paint (complete)

Front



**Bumper grille FL**

Scratch(es)

Replace

Front



**Bumper grille FR**

Missing

Replace

Front




**Door RR**

Bad repair


Repair and paint (complete)

Right



**Tailgate / Boot**

Dent(s)  
Repair and paint (complete)  
Rear




**User's manual**

Missing  
Replace  
Interior

**Windscreen**

Stone chip(s)  
Windscreen repair  
Front



**Tyres**

**Front Left**

Summer  
235/55/18/100/H  
Hankook  
4.0 mm

**Front Right**

Summer  
235/55/18/100/H  
Hankook  
3.8 mm

**Rear Left**

Summer  
235/55/18/100/H  
Hankook  
7.3 mm

**Rear Right**

Summer  
235/55/18/100/H  
Hankook  
7.0 mm

## Checks

CO2 Emission	<b>0</b>	Digital maintenance	<b>Yes</b>
Luggage cover	<b>Yes</b>	Number head rests	<b>5</b>
Number of charging cables (rapid charge)	<b>1</b>	Number of keys total	<b>2</b>
Reset to factory settings	<b>Yes, vehicle is reset to factory settings</b>		<b>N/A</b>
User's manual	<b>No</b>	Service book	

### Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.