

Vehicle details

VIN	5YJ3E7EA3 MF901511	Brand	TESLA	Maintenance date	-
Licence Plate		Model	Model 3 Standard Range Plus RWD	Maintenance mileage	-
Registration date	10/03/2021	Year	2021	Exterior Color	Black Solid
Odometer	128 669 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	06/07/2026				

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Vehicle charger	✓
Wireless charger	✓

Technical Document

Spare key	✓
Card Key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 235/45/18 All seasons 5.5 mm



Michelin 235/45/18 All seasons 5.5 mm



Michelin 235/45/18 All seasons 3.0 mm



Michelin 235/45/18 All seasons 3.0 mm

Exterior

1



Part	Other bodywork
Position	-
Damages	Not conform
Severity	-
Repair mode	For info
Wieldopset los 18 inch.	

2



Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3



Part	Step plate
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Alloy wheel 18"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



Part	Wing
Position	Back right
Damages	Improper repair
Severity	-
Repair mode	Repair

6



Part	Step plate
Position	Back right
Damages	Improper repair
Severity	-
Repair mode	For info

7



Part	Door
Position	Back right
Damages	Improper repair
Severity	-
Repair mode	Repair

8



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

9



Part	Bumper
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

10



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

11



Part	Tailgate / Boot door
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

12



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info