Technician
Rutger Koogh

2-FKC-958

2-FKC-958 · COMBI L2H12.0dCi 150 DCT N-CONNECTA · 27 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FKC-958
Manufacturer	NISSAN
Model	Primastar
Model Versions	COMBI L2H12.0dCi 150 DCT N-CONNECTA
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2024
KW	110

Fuel Type	Diesel
VIN	VNVJ4000073210853
Cylinder Capacity	1.997 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	29-05-2024
Odometer	73.074 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	9

Images
































Accessories

ABS	Fog lights
Airbags	Leather steering wheel
Audio System	Manual air conditioning
Bluetooth car kit	Navigation system
Central door locking	Rear parking sensors
Centre armrest	Rear view camera
Cruise control	Roller cover / parcel shelf
Electric windows front	Steering wheel multifunction
Electrically adjustable exterior mirrors	Tow bar

Condition

Condition exterior	Adequate	Last maintenance odometer	40.011
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	16-09-2025		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Continental	205 mm	75 mm	16 inch	All Season
Rear Left	4 mm	Vredestein	215 mm	65 mm	16 inch	All Season
Front Right	5 mm	Continental	205 mm	75 mm	16 inch	All Season
Rear Right	4 mm	Vredestein	215 mm	65 mm	16 inch	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 mm					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Left Front	Missing	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Scratch(es)	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Small scratch(es)	Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Small scratch(es)	Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Hoekje	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Roof	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Missing	Antenne	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No