



Expertise

Protocol number: 46199602
Order No. / Reference: 26530158
Inspection date: 29 Jun 2026

Manufacturer: Volkswagen

Model: Multivan 2,0 TDI SCR KÜ

VIN: WV2ZZZST9RH018201



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Multivan 2,0 TDI SCR KÜ	
Vehicle Identification number	WV2ZZZST9RH018201
Mileage (Read)	133,535 km
First registration	7 May 2024
Number of holders	1
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Mediumblau Metallic (N5C)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Beige
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	18,400 km
Last service on / at	04/2026 at 121,794 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB036730
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CQJ 00436		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,850 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 102H	Summer tyres on Steel rim with wheel cover	Falken	5mm / 5mm
2)	215/65 R16 102V	Summer tyres on Steel rim with wheel cover	Continental	7mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 102H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/65 R16 102H	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger (with passenger airbag deactivation)
- Evasive steering assist and turn assist
- Exterior mirror housings in high-gloss black
- Floor coverings: Reinforced velour carpet in the passenger compartment
- third brake light
- Three-phase generator 180 A
- Electronic Stability Program, ABS, ASR (with deactivation button), EDS (Hill Start Assist)
- Chassis: Suspension and damping, standard
- Window in the sliding door, left
- Windows: Front pane made of laminated safety glass, heat and sound insulating
- Transmission: DSG (dual-clutch transmission), 7-speed automatic
- Boot lid
- Rear window with wiper/washer system, heated
- Air conditioning with manual control
- Fuel-powered auxiliary heater
- LED taillights
- Steering wheel: Multifunction leather steering wheel with paddle shifters
- Multimedia systems: 2 USB interfaces (Type C) in the dashboard
- Emergency braking assistant "Front Assist" (with pedestrian and cyclist detection)
- Particulate filter: Soot particle filter for diesel engines
- Radio: App-Connect incl. App-Connect Wireless (for Apple CarPlay and Android Auto)
- Radio accessories: 8 speakers (passive)
- Wheels/Tires: 215/65 R 16 102 H XL, optimized for low rolling resistance
- Wheels/Tire Accessories: Wheel covers for 16" wheels
- Sliding door in the passenger/cargo compartment: sliding door on the left
- Keys for locking system: 2 vehicle keys
- Speed-sensitive power steering (Servotronic)
- dimmable interior safety mirror
- Seat covers: Bi-color fabric seat covers, "Bright Dots" design
- Sun visors with mirrors, ticket holder on the driver's side (airbag label on the sun visor and B-pillar on the passenger side)
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with keyless start system "Keyless Start" without safe locking
- Airbag: Side and head airbags for driver and front passenger (head airbags for the outer rear seats - center airbag in the front)
- Reinforced battery (68 Ah/ 380 A)
- On-board tools and tire mobility set (in the storage compartments in the luggage compartment)
- Decorative inlays: Decorative inlays "Scale Light Grey"
- Parking assistance in the front and rear areas
- Deletion: No seats in the 3rd row.
- Chassis: 16" chassis with 16" disc brakes at the front and 16" disc brakes at the rear
- Window in the sliding door, right
- Electric windows, front
- Cruise control system with speed limiter (and "Intelligent Speed Assist")
- Glove compartment without light
- Tailgate closing without interior unlocking function
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- LED headlights with LED daytime running lights
- Strip between the headlights painted in glossy black
- Headlight range control
- Multifunction display: Digital Cockpit
- Fatigue detection
- Non-smoking version
- eCall emergency call system
- Without Mode 3 charging cable
- Radio: "Ready 2 Discover" with 25.4 cm (10 inch) color touchscreen including "Streaming & Internet"
- Radio: Digital radio reception (DAB+)
- Radio accessories: Voice control
- Wheels/Tires: 4 steel wheels 6.5 J x 16
- Wheels/Tires: Tire pressure monitoring system
- Windscreen wiper interval control, 4-stage adjustable (for the front windscreen wipers)
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Seat belt monitoring system (warning tone and light for unfastened seat belts front and rear)
- Seats in the passenger compartment: 3 individual seats facing forward in the 2nd row.
- Lane keeping assistant "Lane Assist"
- Daytime running lights with cornering lights
- Telephone: Mobile phone interface
- Traffic sign recognition
- Green thermal insulation glazing



Extra equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Anti-theft alarm system with interior monitoring, backup horn and tow-away protection • Tailgate: Tailgate with power closing assist (tailgate with power closing assist - power closing of the tailgate with unlocking function from inside) • Rear View reversing camera • Sliding door: Closing aid on both sides for sliding doors (sliding door left and right with closing aid) • Partitions: Mesh partition | <ul style="list-style-type: none"> • Windows (glass type in the cargo/passenger compartment) - rear windows heavily tinted • Paint finish: Metallic • Light & Visibility • Navigation system "Discover Media" (25.4 cm (10 inch) color touchscreen - streaming & internet) • Heated seats for the driver's cab, left and right, separately adjustable |
|--|--|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Rear bumper	Rear bumper (Zusatzkosten können entstehen) - Glued / labelled - De-glue / neutralise
3	Side panel - rear right side	Side panel - dent(s) - Repair and paint

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side right, Provided by user / customer, from 3 Jan 2026	4.501,91 €

Repainting

No.	Repainting
1	Mudguard - right side, Door - rear right side, Professionally carried out

Paint coat thickness measurement

Mudguard - right side	187 µm	Door - rear right side	189 µm
-----------------------	--------	------------------------	--------



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der Winterradsatz ist kein Bestandteil der Ausstattungsliste.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Instrument cluster



Figure 7: Instrument panel



Figure 8: Interior 360° view




Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Additional tyres



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Damage 2: Rear bumper: Rear bumper (Zusatzkosten können entstehen) - Glued / labelled - De-glue / neutralise




Damage 3: Side panel - rear right side: Side panel - dent(s) - Repair and paint



Damage 3: Side panel - rear right side: Side panel - dent(s) - Repair and paint




Repainting 1: Mudguard - right side, Door - rear right side



Repainting 1: Mudguard - right side, Door - rear right side



Mudguard - right side: 187 μm



Door - rear right side: 189 μm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WV2ZZZST9RH018201

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Multivan T7 Kurz

Datum	KM-Stand	Beschreibung
14.04.2026	121.794	Bremsflüssigkeit; Bremsflüssigkeit ern; Getriebeöl ern/prüfen; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
09.09.2025	90.525	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
14.03.2025	59.917	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
09.10.2024	28.316	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges